# **AGENDA NOTE**

# FOR

# THE 21ST MEETING OF THE STATE ADVISORY COMMITTEE

Date	22 <sup>nd</sup> APRIL 2015
Time	11.30 AM
Venue	Gujarat Electricity Regulatory Commission 6 <sup>th</sup> Floor, GIFT ONE, Road 5-C, GIFT City, Gandhinagar 382355, Gujarat India.

AGENDA ITEM NO.	NOTES ON AGENDA
1	Approval of the minutes of the 20 <sup>TH</sup> Meeting of the State Advisory Committee held on 6 <sup>TH</sup> AUGUST 2014.
2	Action Taken Report on the minutes of the 20 <sup>TH</sup> Meeting of the State Advisory Committee
3	Issues raised by the Members.
4	Standard of Performance (SoP) and Monitoring of Performance of CGRFs
5	<ol> <li>Issues for Information of the Committee</li> <li>Petition for Truing up of FY 2013-14 and Determination of Tariff for FY 2015-16.</li> <li>Draft Supply Code 2014</li> </ol>
6	Any other Item with the permission of Chair

<u>Agenda Item No.1:</u> Approval of the minutes of the  $20^{TH}$  Meeting of the State Advisory Committee held on  $6^{TH}$  AUGUST 2014 at Gandhinagar.

The  $20^{th}$  Meeting of the State Advisory Committee was held on  $6^{TH}$  AUGUST 2014 at Gandhinagar. The minutes of the meeting were sent to all the members vide letter No. GERC/VHT/ $20^{TH}$  SAC/2014/1504/1579/1801 dated  $21^{ST}$  AUGUST 2014. No comments were received from any of the members. The minutes may be approved.

<u>Agenda Item No. 2:</u> Action taken report on the Minutes of the 20<sup>TH</sup> Meeting of the State Advisory Committee is as under:

	isory Committee is a	
Item No. Of Minute s	Details of the Item	Action taken Report
Agenda	Update on Crop	UGVCL: UGVCL has renewed its Crop Burning Insurance Policy with
Item No.	Burning - Rejected cases follow up	Oriental Insurance Company Ltd, valid from 6/2/14 to 05/02/2015 & 06/02/2015 to 05/02/2016. Claims details given upto 31/03/15. It also includes insurance for harvested crop.
2.2.	DISCOMs to analyse	
(ii)	the premium amount paid for Agriculture insurance policies and amount paid in	<u>DGVCL:</u> In DGVCL crop compensation policy has been finalized, harvest crop is also incorporated in renewal of insurance policy for the period of one year up to 02.07.2015 and same is circulated to all field offices.
	settled cases.  The committee members raised	PGVCL: PGVCL had undertaken crop Insurance Policy with Oriental Insurance Company. PGVCL has paid 12.36 Lacs towards the premium and Policy in force till 18 <sup>th</sup> August, 2014.
	issue regarding harvested crops need to be covered in Insurance.	MGVCL: The crops insurance policy having insurance cover of Rs.40 lacs and premium of Rs.2.25 lacs + Service Tax of Rs.27810/ (Total Rs.2,52,810/-) and validity upto 02.04.2015 is taken by MGVCL. The possibility of covering insurance of harvest crops will be explored at the time of renewal of policy after validity of existing policy is over.
		DISCOM wise status of Crop Compensation cases is placed at <u>ANNEXURE</u> <u>- A</u>
Agenda Item No.	Maintenance Activities.	<b>UGVCL:</b> Maintenance report up to March-2015 is attached in the format finalized by GUVNL. Format is attached at <u>"ANNEXURE "B"</u> .
NO.		DGVCL: A meeting to review progress of maintenance work was held
2.2.7		at corporate office Surat headed by C.E. DGVCL, wherein maintenance carried out and planning was reviewed.
		A common format sheet showing maintenance carried out in all circles up to February-2015 is attached here with at "ANNEXURE-C".

Agenda Item No.2.9. (2)	Adoption of RF metering system.	PGVCL: A common format sheet showing maintenance carried out in all circles up to March-2015 is attached here with at "ANNEXURE-D".  MGVCL: In MGVCL, the maintenance activity is carried out regularly with planning of pre-monsoon and post-monsoon maintenance of 11 KV lines, LT lines & Transformer Centres and reports are complied in the format given by GUVNL. "ANNEXURE-E" up to March-2015.  UGVCL: The Details of Pilot project along with comments is attached as "ANNEXURE - F"
Agenda Item No. 3	Standard of Performance (SoP) and Monitoring of Performance of CGRFs.  (Action: DISCOMs)	<ul> <li>UGVCL: The performance review and monitoring of field offices is regularly carried out by MD/CE during regular meetings. The performance parameters up to sub division level are critically analyzed. Implementation of orders of CGRF and Ombudsman are also reviewed by MD. As regards electrical accidents it is to state that all efforts are put in to reduce the accidents.</li> <li>The total nos. of accidents is reduced in 1<sup>st</sup> &amp; 2<sup>nd</sup> Qtr. 2014-15 in comparison to corresponding quarters of 2013-14. The details are attached at ANNEXURE "G &amp; H"</li> <li>In addition to various steps as narrated in last ATR of UGVCL dated 25.06.2014, following additional actions are initiated by UGVCL to avoid accidents.</li> <li>An SMS is sent on every Monday to all line staff requesting for following safety regulations, thereby making line staff aware about safety aspects.</li> <li>All Circle heads are directed to monitor records related to safety to be maintained at Sub-divisions. (Copy of letter is attached as ANNEXURE "I".)</li> <li>Safety officer, UGVCL is periodically visiting the field and preparing safety audit report.</li> <li>DGVCL: DGVCL has taken appropriate actions for safety aspects to reduce electrical accident as under: SAFETY MEASURES TAKEN:</li> <li>Wide publicity regarding electrical safety precautions given on FM Radio and news papers during kite festival during safety week.</li> <li>Sheri-natak /road shows were performed by Company staff to educate public at large regarding safety.</li> </ul>

- Safety film was shown to all line staff to create awareness among line staff and Video CD of film AJVALA was distributed to educate line staff and engineers.
- Fencing provided to 6618 Nos. of distribution transformer centres in urban and in highly populated area up to month of SEPT.-2014.
- Safety pamphlets were distributed to spread safety message to public at large.
- Street hawkers and vehicle owners were educated against encroaching near transformers installations. Also they were served notices not to encroach the same.
- Safety booklet and message from our M.D. Containing safety precautions were distributed to all line staff and engineers during safety week.
- Neck Belts were distributed during the kite festival for general safety as a part of corporate social responsibility activity.
- Total 973 Nos. of hoardings informing safety awareness are provided in thickly populated area as well as sub division - division offices.
- DGVCL has provided 464146 Nos. of earth terminal to the installations up till month of Sept.-2014
- Meter replaced in place of old electromechanical meters & road map for replacement of faulty meter for two months.

<u>PGVCL</u>: As regards to electrical accident it is to state that it has reduced year on year. Comparison of the electrical accidents occurred in Distribution network of PGVCL for the first half since 2011-12 is furnished hereunder.

	Year	Fatal	Fatal	Non Fatal	Total
114	2011-12	64	303	94	461
H1	2012-13	75	187	120	382
	2013-14	70	206	89	365
	2014 -15	55	175	85	315

As regards rate of failure of Distribution Transformer, it is to state that we have enhanced our surveillance activity with the focus on the feeders having more than 10% failure rate of Distribution Transformer for detecting the unauthorized load used by consumer, review of loading on Distribution Transformer, maintenance of LT line and Transformer etc. It is estimated that at the end of year we shall achieve reduction in failure rate compared with the previous year.

MGVCL: The post of Safety Officer is created as per GERC norms. The Safety Engineer is visiting sites where electrical accident occurs. For the safety awareness, regular meetings are being arranged with line staff along with JE / DE of s/dn by Safety Engineer to create awareness in line staff. They are educated to use safety tools and tackles and to take all required safety precautions with strict implementation to be ensured by their supervisory staff / officers while working on line. Preventive actions are being taken to avoid the electrical accidents. Fencing work around the distribution transformer centre is started to avoid fatal animal

		accidents. Field offices are instructed to arrange periodical meetings at sub-division, division and circle level wherein the modus operandi of previous accidents to be discussed with line staff and precautions to avoid such accidents to be explored. Press Notes, Press Advertisements are given to create public awareness especially during monsoon, festival of Uttarayan etc.
		No any comments received from CEI and GUVNL in this regard.
Agenda	Pendency of	The Commission constituted the Committee comprising of MD,
Item	Agriculture	PGVCL, MD, UGVCL, Shri Maganbhai Patel, Member SAC, Shri
No. 5	Connection	Kirtibhai Amin, Member SAC under the Chairmanship of the
	applications.	Secretary, GERC to look into the matter of pendency of new
	(Action: Secretary GERC)	

#### AGENDA ITEM NO. 3: ISSUES RAISED BY THE MEMBERS

Issues received from following members are kept as Annexure.

- 1. Shri Shivlalbhai L. Barasia, Rajkot Engg. Association, Rajkot. Annexure K.
- 2. Shri Kirtibhai Amin, Pradesh Kisan Vikas Sangh, Patan. Annexure L.
- 3. Shri K. K. Bajaj, CERC, Ahmedabad Annexure M.
- 4. Shri Maganbhai Patel, Bhartiya Kishan Sangh, Gandhinagar, Annexure N
- 5. Chief Electrical Engineer, Western Railway, Mumbai Annexure O

### AGENDA ITEM NO. 4:- UTILITY WISE SOP AND CGRF REPORTS

Utility wise SOP reports for Quarter - III of FY 2014-15 along with reports of previous three Quarters are kept as <u>ANNEXURE - P</u>

Monitoring reports of CGRFs and Ombudsman for Quarter II & Quarter-III of FY 2014-15 is kept at ANNEXURE- Q

#### AGENDA ITEM NO 5:- Issues for Information of the Committee

# A. PETITIONS FOR TRUING UP OF FY 2013-14 AND DETERMINATION OF TARIFF FOR FY 2015-16

As per the provision laid down in Regulation 29.8 of GERC (Multi-Year Tariff) Regulations, 2011, every utility is required to file their petition for truing up of FY 2013-14 and determination of tariff for FY 2015-16 latest by 30<sup>th</sup> November 2014. Accordingly, all the utilities except KPT and ASPEN have filed their petitions for True-up of FY 2013-14 and Determination of Tariff for FY 2015-16. All the petitions have been registered and Utilities have given wide circulation to solicit views from various Stakeholders and Consumers. The hearings for the said petitions were conducted on

10<sup>th</sup>, 11<sup>th</sup>, 13<sup>th</sup> and 19<sup>th</sup> March 2015 at the Commission's Office. The Commission shall publish the orders on the said petitions in due course.

### **DRAFT SUPPLY CODE 2014**

The Commission has published Draft GERC (Electricity Supply Code and Related Matters) Regulations, 2014 on 11/12/2014 and invited comments/suggestion from various stakeholders by giving public notice in various newspapers and also placing the same on the Commission's website. The said Regulations will supersede the existing Supply Code - 2005 once it is notified. Last date for filing comments/suggestion was kept on 15/12/2014 but, considering requests made by consumers' organization and utility, the time limit for filing comments/suggestions was extended up to 15/01/2015. Total 33 entities including consumers' organizations, individuals, and other State Regulatory Commission have submitted their views to the Commission.

AGENDA ITEM NO. 6:- ANY OTHER ISSUES WITH THE PERMISSION OF THE CHAIR.

Annexure - A

Agenda Item No. 2.2. (ii): Crop Compensation Status

DISCOM	Nos. of Cases Registere d	Approx. Estimate d Loss Amount (Rs. In Lacs)	No. of Cases Settled & Compensa tion Paid	Compensati on paid amount in to Settled Cases (Rs. in Lacs)	Nos. Of Cases Pendi ng	Nos of Cases Rejected	Remark
UGVCL	60	29.43	20	3.83	38	2	1 Due to Stacked Crop & 1 Due to staked Grass Claim Amt. Rs.15.44 Lacs
DGVCL	97	213.62	1	1.79	96	-	For other cases follow up going on with SE & Insurance company dtd: 14.10.2014
PGVCL	77	56.55	29	10.81	10	8	1 Case is pending before a Court. Harvested crop has been included in the renewal policy.
MGVCL	MGVCL 13		7	8.26l	5	1	Nos. Cases 10 all claims are under process for settlement subject required document asked.

ANNEXURE - B: UGVCL - STATEMENT MAINTENANCE UPTO MARCH -2015

								Maint	enance Ac	tivities Carı	ied out u	pto March	-15				
Sr No	Category of Feeder	Nos. of Feede	Planning to complete the maintenan	Nos. of Feeders Complet	Pole Plumbi	Cond. Replaceme	Cond. Restringi	Stay New /	Earthin	Providi		ansforme aintenanc		Tree Cutting (Nos. of	Insu Replac	lator ement	Ideal Villag
		r	ce	ed	ng	nt	ng	Attende d	g	ng ABC	Dist. Box	D.O. Fuse	Earth ing	Locatio ns)	Pin	Disc	e
1	HT EXPRESS	130	130	130	5	0.4	7.0	14	0	0.0	0	0	0	711	86	54	0
2	GIDC	39	39	39	48	1.8	30.0	257	170	0.0	138	314	154	983	404	148	0
3	INDUSTRIAL	305	305	305	375	10.8	246.0	857	593	7.7	569	1145	655	4946	838	483	0
4	URBAN / TOWN	254	254	254	748	34.0	799.0	1650	1350	38.9	1496	3077	910	9661	12963	3419	0
5	JGY	722	722	722	1704	200.0	2314.0	2360	2148	91.5	1967	4664	1108	37691	9199	3983	17
6	AG	2605	2605	2040	2225	348.0	7661.0	2780	3410	0.0	1219	10757	1808	53367	3299	2271	0
	Total	4055	4055	3490	5105	595	11057	7918	7671	138	5389	19958	4634	107360	26789	10358	17

NB Many feeders are maintained more than once in a year, however number of feeders maintained are shown equal to the actual number of feeders

# ANNEXURE - C :: DGVCL - STATEMENT MAINTENANCE (FEB-2014)

			D. 4444	NOS					POLE				ANSFORI AINTENA					NOS OF			
S R N O	CATEGORY OF FEEDER	NO S .OF FDR S	PLANNI NG TO COMPLE TE THE MAINTE NANCE	NOS OF FEEDE RS COMP LETED	POLE PLUM BING	COND. REPLAC EMENT	COND. RESTRI NGING	STAY NEW / ATTE NDED	EART HING NEW / RE- ACTIV ATED	PROVI DING U/G CABLE	PROVI DING ABC	DIST. BOX	D.O. FUSE	TC EART HING NEW / RE- ACTIV ATED	TREE CUTTI NG	DISC INS. REPL ACED	PIN INS. REPLAC ED.	VILL AGE TO MAK E IDEA	H.T. LINE	L.T. LINE	X'MER S
		UNIT			NOS	KM	KM	NOS	NOS	KM	KM	NOS	NOS	NOS	LOCAT IONS	NOS	NOS	NOS	KM	KM	NOS
1	AG	332	153	58	8832	160	1257	929	943	1	43	1317	1648	2560	18940 6	2913	3397	3	8073	1263	3997
2	JGY	356	150	61	8009	409	1065	1098	1647	6	983	2533	2184	1996	18572 8	3782	5271	26	8700	1437	5420
3	URBAN/ TOWN	243	174	133	1506	164	708	473	1038	22	171	2566	1945	1895	78253	962	1634	6	2784	1078	6250
4	INDUSTRIAL	244	168	129	994	119	158	201	364	14	10	500	607	554	28685	218	1027	0	1363	158	2832
5	GIDC	114	90	145	683	76	113	328	331	1	1	272	595	288	40281	452	864	0	652	70	942
6	HT EXPRESS	180	132	78	386	11	48	149	192	2	46	53	37	49	16524	233	1094	0	565	64	93
	Circle Total	1469	867	604	20410	940	3350	3178	4515	45	1254	7240	7016	7342	53887 7	8560	13287	35	2213 7	4071	19534

# ANNEXURE - D :: PGVCL : STATEMENT MAINTENANCE UPTO MARCH-2015

Category	Total Nos of	Planning to Complet	Nos of Feeders	Inclind Pole Made Stright / Pole	Conductor Replacement	Conductor Restringing	Stay/Guy Provided /	Earthing Reactivete d	Provi- ding U/G	Provi- ding		RANSFORME 1AINTENANG		Location Tree	Disc Insulato r	Pin Insulato r
Category	Feeder s	e Nos of Feeders	Complet ed	Plumbing (Nos)	(Km)	(Km)	Attended (Nos)	/ New (Nos)	Cable (Km)	ABC (Km)	Dist Box (Nos)	Do Fuse (Nos)	Earthin g (Nos)	cutting (Nos)	Replace d (Nos)	Replace d (Nos)
AG	2754	1636	1416	27813	1403.08	85409.00	15362	19843	0.00	175.86	4510	10302	6686	116621	13738	28838
JGY	1188	719	494	7535	598.79	18086.00	4043	12408	0.00	1673.05	2556	5222	3805	35882	5193	13148
URBAN	681	579	469	1772	286.17	9681.00	1585	4032	16.29	562.42	6309	16492	6672	35349	2377	7555
IND	343	114	65	607	57.15	2189.00	390	972	0.00	17.24	207	613	207	5432	478	1708
GIDC	64	39	44	59	24.00	618.00	75	426	0.00	0.16	110	150	151	1645	194	575
HT EXP	190	42	12	60	1.12	148.90	33	64	0.00	5.84	25	25	39	276	29	70
OTHER	83	73	0	4	0.45	6.00	7	3	0.00	0.00	4	1	7	5	9	6
TOTAL	5303	3202	2500	37850	2370.76	116137.90	21495	37748	16.29	2434.57	13721	32805	17567	195210	22018	51900

ANNEXURE - E: MGVCL: STATEMENT MAINTENANCE - UP TO MARCH - 2015

Category	Total Nos. of Feede	Plan ning to com	Nos. of Feed ers	Incline d Pole made Straigh	Conduct or replace ment	Conduc tor Restrin ging	Stay/Guy provided/At tended (Nos)	Earthing reactivete d/New (Nos)	Provid ing U/G Cable	Provi ding ABC (Km)	TRANSFORMER MAINTENANCE			Location Tree cutting (Nos)	Disc Insul ator Repla	Pin Insula tor repla	Ide al Vill age
	rs	plete Nos. of feed ers	Com plet ed	t/ Pole Plumbi ng (Nos)	(Kms)	(Km)			(Km)		Dist. Box (Nos)	DO Fuse (Nos )	Earthi ng (Nos)		ced (Nos)	ced (Nos)	
AG	477	477	477	2111	253	915	2793	3032	0	265	1769	3523	2409	91937	1560	2241	
JGY	386	386	386	2218	286	946	3389	8495	1	668	2673	4042	3537	103678	1643	2672	141
URBAN	286	286	286	831	56	239	1460	1789	23	170	1463	1647	1712	21934	399	693	
IND	87	87	87	135	25	38	149	214	2	4	226	217	96	3495	210	220	
GIDC	70	70	70	75	5	13	100	158	1	1	95	101	127	2948	58	92	
HT EXP	130	130	130	65	6	14	84	176	0	0	8	0	25	2288	128	92	
TOTAL	1436	1436	1436	5435	631	2165	7975	13864	27	1109	6234	9530	7906	226280	3998	6010	141

Note: The EHT category feeders (55 Nos) are not mentioned above as the Maintenance is not being carried out by MGVCL

**11 |** P a g e

## ANNEXURE - "F"

#### **RF Metering Pilot Project Details**

UGVCL decided to procure RF meters as a future of metering in distribution sector. UGVCL tendered for initial procurement of 30000 meters. Only 2 vendors qualified for supply, L&G Meters & HPL Meters. During meeting regarding fulfilment of inter-operable communication facility (This was also a condition in the tender) agreement could not be reached between the two vendors and therefore initially an order of 1000 meters was given to each vendor. Proto sample is approved of these vendors with some suggestions/comments. Supply is yet to be received.

Meanwhile it was decided to call the interested RF module manufacturers for supply of meters with common interoperable module. Six vendors showed interest. Each of them was instructed to install about 100 meters with their modules which after study is to be made inter-operable for reading with a common MRI having common protocol. 3 out of 6 vendors viz. M/s CYAN, MILANGE & N-Konnect installed about 100 meters each at suggested locations. As environment was different for these installations the data collection rate was not comparable. Also two of the vendors requested to provide improved module for better data collection.

It was therefore decided to collect 20 more meters from all these three vendors. Two of the vendors provided new meters with improved module and third one opted for earlier provided meters. All these meters were installed at twenty locations (3 meters at each location of different makes) under no load condition. Readings were taken from different angles and distances. Data collection rate is ranging from 50% to 95% for different vendors.

A meeting was held on 24/12/14 to discuss regarding inter-operability agreement amongst the vendors so that a common RF module is finalized for UGVCL which would be open for meter suppliers to adopt and make their meter communicable as per requirement. The process of module finalization is presently in progress.

The first phase of field testing encompassing all the consumers of a sub-division following the above procedures would take about 4-5 months. Thereafter the suppliers of the module manufacturers would gradually be increased and scope spread of RF meters would be scaled-up.

# Annexure - G

## **Report on Accidents**

# ACCIDENTS OCCURRED DURING (July- Sept 13 & July- Sept 14 )

		No. o	of accid	lents in	July-	Sept 13		No. of	accide	ents	in July	- Sept 14	
SR NO	Name of Circle	De	pt.	Out	sider	Animal	Total	Dept	t.	Out	sider	Animal	Total
		FH	NFH	FH	NFH	Allillat		FH NFH		FH NFH		Allillat	
1	Sabarmati	1	1	8	3	17	30	0	2	6	2	19	29
2	Mehsana	1	1	9	0	4	15	0	1	6	1	8	16
3	Palanpur	0	0	8	6	12	26	0	1	4	0	10	15
4	Himmatnagar	0	0	13	1	13	27	0	1	4	1	14	20
	Total			38	10	46	98	0	5	20	4	51	80

FH--Fatal Human , FA--Fatal Animal , NFH--Non-fatal Human


# Annexure - H :: Report on Accidents

# ACCIDENTS OCCURRED DURING (April- Sept. 13 & April- Sept. 14 )

		No.	of accid	dents	in April-	Sept. 13		No.	of acci	dents 14		il- sept	
SR NO	Name of Circle	De	pt.	Ou	tsider	Animal	Total	De	pt.	Out	sider	Animal	Total
		FH	NFH	FH NFH		Allillal		FH	NFH	FH	NFH	Allillat	
1	Sabarmati	1	1	17	6	24	49	0	3	13	4	23	43
2	Mehsana	1	1	11	-	7	22	0	3	9	2	8	22
3	Palanpur	0	2	11	9	19	41	0	4	9	3	13	29
4	4 Himmatnagar		0	18	2	19	39	1	3	9	2	18	33
	Total	2	4	57	19	69	151	1	13	40	11	62	127

FH--Fatal Human, FA--Fatal Animal, NFH--Non-Fatal Human

**ANNEXURE - I: UGVCL** 



CIN - U40102GJ2003SGC042906

No. UGVCL/Regd/DSM & Safety/2.53

Date: 0 4 DEC 20

To,
The SuperIntending Engineer
UGVCL, Circle Office,
Mehsana/ Sabarmati/Palanpur/Himatnagar

Sub: Inspection of Sub-division offices for issues related with safety of line staff and observance of safety procedures

With the continuous rise in population and massive infrastructure development, the electric network has become a potential risk for accident. It is becoming a serious safety threat for human and animal life.

Avoiding or reducing accidents in electrical network is a serious challenge. It necessitates actions from company as well as employees and common public. It calls for colossal effort for revamping of network with setting up of strict monitoring arrangement

The main cause of accident is unsafe/ inadequate clearances, intentional/ unintentional access to the live electrical line, lack of awareness about the hazards of electricity, improper method, poor workmanship and unsafe installations. The threat further increases due to lesser or poor maintenance, resources crunches, uses of substandard material by consumers and increasing trend to flout the existing laws.

Considering the growing size of network and its risk for human and animal life, various ways to mitigate the risk of accidents have been under focused consideration at various administrative levels of the Company.

With a view to analyze the root causes of accidents and measure to prevent them or so at least to ensure that, the situation does not worsen in the coming years, it is decided that SE (DSM and Safety) will make frequent visit of subdivisions. SE (DSM & Safety) will convey proposed date of inspection to concerned EE and DE of s/dn office directly and in advance. He will indicate the probable steps to be taken by the concern SDO regarding safety precaution and stringent monitoring on line staff and electrical contractors.

Accordingly, Following Registers/Points needs to verify during Inspection:

- Line staff program register
- (2) Tools and Tackle register
- (3) Line staff Meeting register

11211

inspection of Sub-division offices .DOC

Regd. & Corporate Office: Visnagar Road, MEHSANA - 384 001 (North Gujarat) - 1 Telephone: (02762) 222080-81 Fax: (02762) 223574
e-mail: corporate@ugvcl.com

# ANNEXURE - I PAGE2 UGVCL



CIN - U40102GJ20035GC042906

### 1/2//

- (4) Electrical Inspection of New HT/LT and T/C (5)
- Test Report verification (6)
- Checking of new line works and service connections (1-Q & 3-Q) (7)
- (8)
- Compensation cases pending for Human and Animal Accidents Civil suits for accident cases (9)
- (10)Ideal village works
- issue of notice for illegal construction/Encroachment (11)(12)
- Line shifting pending work
- Removal of Idle HT/LT line and T/C (13)
- Removal of crossing (14)
- Removal of channel wires/Hoardings/Telephone wires (15)(16)
- Fencing work progress and onsite visit (17)
- Progress of Earth terminal in existing connections (18)
- Providing of location number and name of feeder on HT poles & TC

Please note as above and pass on suitable directives to all field offices under your control to provide co-operation for required visit and to take subsequent

Chief Engineer (op) UGVCL, Mehsana

# Copy to,

EA to MD, UGVCL, Mehsana

ACE (T)/SE (T), UGVCL, Mehsana

"ANN EXURE - 0"

# Report

on

the various issues pertaining to application for

**Agriculture Connection** 

# **Before**

The Gujarat Electricity Regulatory
Commission

Date: 20.02.2015

Report on the various issues pertaining to application for Agriculture Connection

#### BACKGROUND

Agriculture is one of the important economic activities of the Gujarat State. Agriculture in the State is largely dependent upon rain and thereafter on ground water. Over a period, with the efforts of the State Government and farmers themselves, a concept of rainwater harvesting has been widely implemented. Because of such efforts, ground water level has come up enabling farmers to cultivate in almost all the three seasons. With the availability of electricity for irrigation purpose and installation of electric pump set for fetching ground water, and because of some natural reasons too, the water level depleted drastically. There are some areas in the State where ground water level depleted below an acceptable limit and hence such areas were declared 'Dark Zones' by the State Government. However, With the implementation of Jyoti Gram Yojana for supplying 24/7 supply to village households and supply of 8 hours continuous power to the agriculture pump sets, the level of ground water has started increasing in most part of the State.

As stated above, the requirement of ground water for irrigation purpose is inevitable in the State. With the expansion of Distribution Network in the interiors of the State, the farmers started switching over from diesel pump sets to electricity pump sets causing a long list of application for having new electricity connection.

Repeatedly, at various forums including during the hearing of tariff petitions of DISCOMs, during the meetings of State Advisory Committee (SAC) and State Coordination Forum issue of pending agriculture connection applications was discussed. Apart from the pendency of such applications, some more issues also came up which relates the usage of electricity for irrigation purpose. Individual farmers and consumer organizations also raised the similar issues before the Commission through separate letters. DISCOMs are also facing some genuine problems in addressing all the issues pertaining to agriculture connections in time bound and effective manner.

During the 20<sup>th</sup> Meeting of the State Advisory Committee and 15<sup>th</sup> Meeting of the Co-ordination Forum, the issues related to agriculture connections once again came up before the Commission. After deliberation with the members of the Committee and the Forum, the Commission felt it appropriate to constitute a committee to

Report on the various issues pertaining to application for Agriculture Connection

discuss all the issues in detail and submit a report to the Commission. The Committee constituted by the Commission comprises of

- 1. The Secretary- GERC as Chairperson of the Committee and;
- 2. Managing Director- Paschim Gujarat Vij Company Limited,
- 3. Managing Director- Uttar Gujarat Vij Company Limited,
- 4. Shri Maganbhai patel Member of the SAC,
- Shri Kirtibhai Amin- Member of the SAC as members of the Committee.

Subsequently, I/c Chief Engineer (Tech) - Gujarat Urja Vikas Nigam Limited was included as member of the Committee.

The members of the Committee met two times i.e. on 5<sup>th</sup> September, 2014 and 23<sup>rd</sup> September, 2014 at Gandhinagar and Rajkot respectively to deliberate on the issues pertaining to agriculture connections. The Committee found following three issues, which is of the prime importance for the applicant seeking usage of electricity for irrigation purpose;

- 1. Huge pending list of new agriculture connection applications;
- Allowance of 2<sup>nd</sup> agriculture connection in the same survey number where the farmer is already having an agriculture connection; and
- Splitting of contracted load in the existing agriculture connection to facilitate more number of sources of water.

During the discussion, following facts came to the knowledge of the members of the Committee;

# 1. Pending Agriculture Connection Applications in the four DISCOMs:

# Madhya Gujarat Vij Company Limited (MGVCL)

As reported by MGVCL, there is no pending agriculture application registered prior to year 2009. There are total 41356 nos. of applications pending as on 31<sup>st</sup> March 2014 which are of the year 2010 and after. Out of 41356 applications, estimates for 2105 applications are issued but not paid by the applicants and payments of estimates for 3098 applications are received. Thus, there is net 36153 applications are pending on the side of MGVCL.

Report on the various issues pertaining to application for Agriculture Connection

### Dakshin Gujarat Vij Company Limited (DGVCL)

There is no agriculture connection application pending with DGVCL. Only 126 applications of Dark Zone area are pending due to non-fulfillment of criteria laid down for availing connections in dark zone by the applicants.

## Uttar Gujarat Vij Company Limited (UGVCL)

As on August 2014 there are total 78640 applications pending. Out of the total applications pending, 68720 applications are for availing connection in Dark Zone area and 9177 applications for availing connection in Non Dark Zone area and 743 applications for availing connection in tribal area. The year wise break up is attached herewith as Annexrue A.

# Paschim Gujarat Vij Company Limited (PGVCL)

As on August- 2014, there are 33615 pending applications in dark zone area and 265008 applications pending in non- dark zone area. Thus there are 298623 pending application in PGVCL. The year wise breakup is attached herewith attached with Annexure-B.

As reported by each Discom, it can be seen that there is no pending application in DGVCL & there is very less numbers of pending applications in MGVCL.

In case of UGVCL, applications up to year 2010 for connections in Non Dark Zone area and applications up to year 2011 for connections in tribal area have been cleared. There are total 54 applications in Dark Zone area pending which were registered between 1990 to 2003. All these 54 applications are pending because of requirement of submission of some documents from applicants' side.

In case of PGVCL, there are pending application since 1990 in dark zone area and since 1996 in non-dark zone area. During the meeting, PGVCL confirmed that all the pending application registered up to year 2000 shall be cleared by March-2015 and all the application registered up to year 2007 shall be cleared March-2016. It can be seen from the Annexure B that from 2008 the flow of new applications increased tremendously to the tune of around 25000 applications per year up to 2010 in the year 2011, 2012 and 2013 around 42000,73000 and 43000 new applications received respectively. In the year 2014, around 24000 new

Report on the various issues pertaining to application for Agriculture Connection

applications received. Thus there are more numbers of applications received in each year than connections released by PGVCL (around 45000 connections each year) resulting in to huge back -log of the applications.

For clearing the back-log, the issue faced by DISCOMs are as under;

### A. Limited capital resources:

Based on the historical data, it is found that capital expenditure incurred in releasing one agriculture connection is around 1.5 Lac rupees. Thus to release all the pending applications at a stretch, a huge capital is required which in turn shall term to tariff increase for all the categories of consumers.

### B. Limited man power resources:

DISCOMs have created separate task force for surveying new applications and supervising the network erection work. However, the work of erecting network is entirely done through contractors who have also limitation of availability of labour force.

# C. Limited Availability of Material:

The suppliers supplying goods like transformers, conductors, poles etc. are having limited capacity to produce goods in given period.

### D. Limited Time Period available for execution of works:

All the execution works related releasing agriculture connection need to be done in the fields. Out of the twelve months in a year, only four to five months period is available for network erection as during the other period fields are not free.

Looking to the above, it is felt by the members of the committee that the pending application can be released in phased manner only. The road map given by PGVCL for clearing the applications registered up to the year 2007 found realistic. The number of application registered in each year after 2007 is very large in case of PGVCL. The members of the committee appreciated the fact that the road map cannot be devised for clearing the application registered after year 2007 as quantum of network requirement cannot be anticipated today because there will be

Report on the various issues pertaining to application for Agriculture Connection

considerable modifications in the network in major part of the PGVCL area on account of connections released for to the applications registered up to 2007.

There are no pending applications in case of UGVCL, which are older than year 2011. The figure of pending applications appears large because around 68000 applications are registered for availing connection in Dark Zone area between year 2012 and August 2014. Looking to the less number of applications pending with UGVCL and the number of connections being released every year by UGVCL it can be presumed that there shall not be any backlog with them after two years.

- Allowance of 2<sup>nd</sup> agriculture connection in the same survey number where the farmer is already having an agriculture connection
- Splitting of contracted load in the existing agriculture connection to facilitate more number of sources of water

As issues no. (2) & (3) are interconnected; it is deliberated together as under;

GUVNL vide its minutes of a meeting held with the MDs of DISCOMs in the month of July, 2012 decided to stop releasing second agriculture connection in same survey number where the farmer is having an agriculture connection. To justify the decision taken by GUVNL, they have stated that there are number of farmers who are waiting for even a single connection in their farm where as on the other hand, some farmers are getting second connection. GUVNL/DISCOMs stated that GoG is giving fixed amount of subsidy against the use of electricity for agriculture purpose. It is not desirable to distribute the share of such subsidy amongst the same set of farmers depriving some farmers who are still waiting for a single connection. GUVNL/DISCOMs expressed that with the limited resources they have; it is the prime requirement of the time to facilitate those farmers who are at all not having access to the electricity for the irrigation purpose and thereby benefitting them too of the GoG subsidy. GUVNL/DISCOMs confirmed that second connection is being given to the framer if his land is divided into more than one survey number.

Report on the various issues pertaining to application for Agriculture Connection

The non-official members emphasized that more than one electric connection is must where the area to be irrigated is very large. Only one connection cannot lift the required quantity of water from the given source, as power supply is available for 8 hours in a day only. It is opined that utilization of electricity either by the same farmer having large survey number and the farmer who does not have any connection, shall be for irrigation of the land only. In both the cases, with release of a connection, irrigation area for the State as a whole shall increase. Thus, second or more connections should be released. DISCOMs may lay a condition for shifting/ transfer of such connection including a condition that such second connection may be made liable for disconnection in case source of water is dried up.

The non-official members stated that just to obtain second connection, a farmer is required to divide his land into different survey numbers. According to them, the process for dividing a land into different survey number is lengthy, time consuming and costly. Instead of pushing the farmers into such cumbersome and costly procedure GUVNL/DISCOMs should not insist for different survey number for obtaining more than one connection. It is also opined that if GUVNL/DISCOMs does not want to give second connection in same survey number then second motor from the existing connection within the limit of contracted load should be allowed to such farmers who has been or would be denied on the ground of having one connection.

Regarding the issue of allowance of second motor from the existing connection GUVNL/DISCOMs stated that Hon'ble High Court in its order dated 8<sup>th</sup> February 2008 upheld the stand taken by DISCOMs for not allowing second motor in the same connection. Hon'ble Supreme Court has also upheld the decision of Hon'ble High Court on the same matter. Thus, as per the decisions of the Supreme legal Authority splitting of load cannot be allowed. DISCOMs presented the copies of the orders of the Hon'ble High Court and Hon'ble Supreme Court which are attached here with Annexure-C&D.

Report on the various issues pertaining to application for Agriculture Connection

### Recommendation of the Committee:

- There is more numbers of pending applications with PGVCL and UGVCL only. GUVNL should organize its resources to clear the backlog in time bound phase manner.
- PGVCL may implement plan to clear application registered up to the year of 2007 latest by March, 2016.
- Second agriculture connection in the same survey number can be allowed through installation of solar pump sets or by recovering full cost of distribution infrastructure from the prospective applicant.
- Splitting of contracted load of existing connection should not be allowed as per order of the Supreme Legal Authority.

This report is put up before the Gujarat Electricity Regulatory Commission for perusal.

Secretary-GERC

Ammenur - A

### Uttar Gujarat Vij Co Ltd,

Performa-5 Status of Agewise Registered Pending AG Connection Applications

Aug.14

Sr.			A Age mae	NAME									_				l Pe	ndi	ng A	<b>\pp</b>	lica	tion	s (L	Jn-s	urve	yed + S	urveye	1)		
No •	name	Distric t	Taluka	OF SCHE ME (TASP/ SPA	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2002	2006	2007	2008	2009	2010	2011	2012	2013	2014	Total
1	Himatna	agar		TASP	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	21	468	489
2	Palanpu	ür		TASP	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	98	156	254
		UGVCL	Total		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	119	624	743
1	Mehsan	ia		NDZ	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	22	129	151
2	Sabarm	ati		NDZ	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	135	741	436	1312
3	Himato	agar		NDZ	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	871	685	4078	1893	7527
4	Palanpu	år		NDZ	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	47	140	187
	Towns.	UGVCL	Total		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	871	820	4888	2598	9177
1	Mehsan	1a		674	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	9685	902	696	11283
2	Sabarm	ati		0/2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	4997	583	346	5926
3	Himatn	agar		DZ	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	8640	487	591	9718
4	Palanpi	ŭr		DZ	2	4	4	2	3	4	0	11	11	3	7	0	2	1	0	0	0	0	0	0	0	0	38750	1722	1267	41793
	100	UGVCL	Total		2	4	4	2	3	4	0	11	11	3	7	0	2	1	0	0	0	0	0	0	0	0	62072	3694	2900	68720
1	Total	UGVCL	5.00	1	2	4	4	2	3	4	0	11	11	3	7	0	2	1	0	0	0	0	0	0	0	871	62892	8701	6122	78640

Annerore.

# YEARWISE REGD. PENDING AG. NORMAL APPLICATIONS (SURVEYED & UNSURVEYED), (Dark+Non Dark Zone)

Month: upto Aug-14

DARK ZONE

SR. NO.	Name of Circle	1980	1991	1992	1991	1991	1995	1396	1997	1998	1999	2000	2001	2002	2003	жож	3002	2006	2002	2008	9000	2010	2011	2012	2013	2014	Total
1	Rajkot-R																-				-						5
2	Morbi	0	0	0	2	1	12	55	6	6	0	3	2	3	1	0	0	n	0	0	0		0	14	13	4	132
3	Porbandar	0	111	119	71	68	107	115	84	86	101	101	38	80	75	0	0	0	0	0	0	c	0	9355	1235	281	12068
4	Junegadh	5	106	68	27	48	36	42	37	82	76	65	18	34	50	0	1	0	0	0	0	0	0	6309	489	19C	7523
5	Jamnagar	1 - 2								-	-/-			-		-	-	-		-	-	-	4	0303	463	190	7363
	Bhuj	0	0	0	0	0	0	0	0	0	0	0	n	0	0	0	0	0	0	0	0	C	0	9465	354	310	10159
7	Surendranagar				-				_	1		-	-			-	-	-		-	-	-		3403	334	2.0	_ ^
	Bhavnagar											FT 55						7		-			-	-		-	0
	Botad																		_		-		-	-	-		0
_	Amreli	8	60	15	12	9	15	5	35	6	14	10	4	5	10	0	0	0	0	0	0	0	0	3000	204	171	3593
	THE RESERVE OF THE PERSON NAMED IN		271	207	117	176		217	162	180	191	175	62	122	136	-	1	0	0	0	0	0	0	28183	2125	957	23515

#### NON DARK ZONE

SR. NO.	Name of Circle	1990	1961	1992	1983	1994	1998	1998	1997	1998	9661	3000	2001	2007	3003	2004	2002	3006	2007	3008	2009	90100	2011	2013	2013	2014	Tutal
	Rajkot-R	0	0	0	c	0	C	165	501	979	789	720	222	684	939	231	329	1970	3298	7374	10262	6889	8484	7457	7684	3509	52986
2	Morbi	0	0	0	c	0	0	0	0	0	0	0	0	0	0	0	0	0	25	688	1242	986	2544	3644	2660	1400	13189
3	Porbandar	0	0	0	0	0	C	0	0	0	0	0	0	0	0	0	0	0	0	326	693	550	1588	2698	2441	1022	9318
4	Junegadh	0	0	0	0	0	С	0	0	0	0	2	31	92	128	76	38	107	106	583	966	1373	2358	3580	3509	1719	14668
5	Jamnagar	0	0	0	0	0	C	307	312	356	716	690	159	574	689	380	885	1730	2389	5287	5187	3981	7180	6926	6347	5033	19128
5	Bhuj	0	0	0	0	0	c	0	0	0	0	0	0	0	0	0	0	0	0	258	329	313	2565	2317	2474	1321	9577
7	Surendranager	0	0	0	0	0	0	0	0	0	0	0	0	0	0	45	79	447	618	1195	1116	1289	2945	2404	2632	1546	14616
8	Bhavnagar	0	0	0	0	0	0	0	52	385	277	265	157	437	342	63	46	118	693	2192	2932	2554	5038	5476	4151	1915	27093
9	Botad	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	685	1722	2228	1926	3617	2879	2878	1366	17301
10	Amreli	0	0	0	0	0	0	0	0	0	0	205	128	70	171	156	113	443	1180	5674	6617	5537	6551	8259	6645	4383	47132
SCHOOL STREET	Total	-0	486	300	B 55	0	255 m 550	672	MARKS	1720	1782	1887	897	1857	2219	951	1990	4815	8994	26299	31572	25398	42870	45640	41621	23314	265008

### TOTAL

SR. NO.	Name of Circle	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2034	2005	3006	2007	2008	2009	2010	2011	2012	2013	2014	Total
1	Rajkot-R	0	0	0	С	0	С	165	501	979	789	720	222	684	939	231	329	1970	3298	7374	10262	6889	9484	7457	7684	3509	52985
	Morbi	0	0	0	2	1	12	55	6	6	0	3	2	3	1	0	0	0	25	688	1242	986	2544	3658	2673	1404	13311
3	Porbandar	0	111	119	71	68	107	115	84	86	101	101	38	80	75	0	0	0	0	326	693	550	1588	12093	3676	1304	21386
	Junagadh	5	106	68	27	48	36	42	37	82	76	67	49	126	178	76	39	107	106	583	966	1373	2358	9889	3998	1909	22351
	Jamnagar							307	312	356	716	690	159	574	689	380	885	1730	2389	5287	5187	3981	7130	6926	6347	5033	49128
	Bhuj	0	0	0	0	0	0	0	0	0	0	0	0	0	. 0	0	0	0	0	258	329	313	2565	11782	2858	1631	19736
	Surendranagar	0	0	0	0	0	0	0	0	0	0	0	0	0	a	45	79	447	518	1195	1116	1289	2945	2404	2032	1646	:4616
_	Rhaymanar	0	-	-	•	-	-			-					-	-62		747	210	1133	4410	2203	2343	2404	2032	7940	74070

BUSE

IN THE HIGH COURT OF GUJARAT AT AHMEDABAD

SPECIAL CIVIL APPLICATION No. 296 of 2008 To

SPECIAL CIVIL APPLICATION No. 306 of 2008 With

SPECIAL CIVIL APPLICATION No. 311 of 2008 To

SPECIAL CIVIL APPLICATION No. 320 of 2008 With

SPECIAL CIVIL APPLICATION No. 357 of 2008

To

SPECIAL CIVIL APPLICATION No. 364 of 2008

## PINAKIN CHANDUBHAI PATEL - Petitioner(s) Versus

THE MADHYA GUJARAT VIJ CO. LTD & 1 - Respondent(s) 

Appearance :

A . NE. 209

SCA NOS. 296/2008 TO 306/2008 WITH SCA NOS.311/2008 TO 320/2008.

MR NIKHIL S KARIEL for Petitioner(s): 1, MS LILU K BHAYA for Respondent(s) : 1 - 2.

SCA NOS. 357/2008 TO 364/2008 MR B S PATEL for Petitioner(s) : 1, MS LILU K BHAYA for Respondent(s) : 1 - 2.

CORAM : HONOURABLE MR.JUSTICE AKIL KURESHI

Date: 08/02/2008

#### ORAL ORDER

1. The petitions arise in somewhat peculiar factual background. The petitioners are agriculturists. one electric already enjoying They were connection from the Madhya Gujarat Vij Co. Ltd respondent No.1 herein to enable them to operate the existing tube wells. Apparently, respondent No.1 herein was of the opinion that tube wells, the number of large the power agriculturists draw more

2/5

sanctioned horse power. By way of general amnesty, therefore, a scheme was introduced calling upon the agriculturists to apply for increasing the existing horse power of their electric connection. There is no doubt in my mind that the entire scheme was for increasing the existing power supply and not for giving independent additional power connection to the same consumer.

work

2. Despite the above clear position, which has also been interpreted and accepted by three decisions of this Court, reference to would be made here-in-after, the petitioners applied to the Board under the said Scheme for separate power connection. Exact nature of their applications made to the Board is not necessary to be gone into in the facts of this case. Fact however, remains that the petitioners erected additional tube wells in their lands and under the guise of availing of additional power supply, obtained separate connection for their new tube wells. It is the case of the Board that very soon they came to know about such gross the scheme. Board therefore, of immediately withdrew the scheme. By which time, number of agriculturists large however, including the present petitioners had already got separate power connections for their newly erected tube wells. When the Board tried to disconnect their power supplies in their second

3/5

tube well, the petitioners resisted by filing

ORDER

civil suits. In this group of petitions, since the trial Court rejected exh.5 applications of all the petitioners, they have approached the District Court and their Misc. Appeals having been dismissed, have approached this Court.

3. The issue is no longer res-integra. As many as three learned Judges of this Court have held that Board was justified in disconnecting the power connections. It was found that the scheme was only for increasing the load of the existing power connection and not for granting individual additional power lines. Such orders are produced by the petitioners along with these petitions. Insofar as interim orders passed by the Courts below are concerned, the same are perfectly in consonance with the above decisions of the High Court. The petitioners therefore, cannot insist on continuing with their irrigation activities through second tube well which they have erected and obtained power connection thereon from the Board. Significantly, permitting the petitioners to continue to use such power supply would also be prejudicial to large number of farmers who might be waiting in line to receive their power connections. Though there is some dispute about the waiting period currently, there dispute that there are farmers who are waiting in line to receive power connections since years.

4/5

- in 1 -

OROPE

- 4. In view of the above discussion, I do not find that the petitions can be entertained. However, one harsh and somewhat peculiar fact cannot be totally lost sight of. Power connections were given as far back as in April 2006. Nearly two years have passed since then. Petitioners have against disconnection protected different orders so far. It is stated on behalf of the petitioners that the petitioners have standing crops on their fields which they have irrigated through their tube wells. They have invested huge amount of money in constructing the tube wells. Therefore, it would be in the fitness of things that the petitioners despite dismissal of these petitions, may continue to enjoy the power connection for a reasonable period to permit them to complete their crop season. It is stated that cotton crop is cultivated in large area and that such crop will wither and suffer irreparably if irrigation facility is abruptly discontinued.
- 5. Considering the totality of facts and circumstances of the case peculiarly arising in these petitions and not to make this formula a precedence, following directions are issued:
  - Respondent No.1 Board shall not disconnect.
     the power supply of the petitioners on their second tube well till 30.5.2008.

300

SPERM

- 2) This is conditional on the petitioners continuing to pay the electric bills of both the connections and to clear the arrears, if any, latest by 15.3.2008.
- 3) They will also file an undertaking within three weeks from today before this Court that after 30.5.2008, they shall not resist disconnection of the second power supply.
- 4) If they apply to the Board for being given additional connection in accordance with the Board's Rules and Regulations, their applications will be considered of-course subject to the same being permissible. Their applications may however, be granted seniority from the date they were actually, though erroneously, granted such connections.
- With these directions, the petitions are disposed of.

(Akil Kureshi,J.)

(raghu)

Annenure - D

ITEM NO.1

COURT NO.10

SECTION IX

SUPREME COURT OF INDIA
RECORD OF PROCEEDINGS

303494

Petition(s) for Special Leave to Appeal (Civil) No(s).5492-5508/2008

(From the judgement and order dated 08/02/2008 in SCA No. 297-303/2008 & SCA No.305-306/2008 & SCA No.311-313/2008 & SCA No.315-317/2008 & SCA No. 319-320/2008 of The HIGH COURT OF GUJARAT AT

JAYENDRABHAI MULJIBHAI PATEL ETC.

Petitioner (s)

**VERSUS** 

MADHYA GUJARAT VIJ CO.LTD & ANR.

Respondent(s)

(With prayer for interim relief) (for final disposal)

Date: 28/04/2009 These Petitions were called on for hearing today.

CORAM :

HON'BLE MR. JUSTICE MARKANDEY KATJU HON'BLE MR. JUSTICE H.L. DATTU Certified to be tree oase

Assistant Registra Just

For Petitioner(s)

Mr. Raju Ramachandran, Sr. Adv.

Mr. Gaurav Agrawal, Adv. Mr. Nikhil Kariel, Adv.

For Respondent(s)

Mr. Shyam Divan, Sr. Adv.

Ms. Hemantika Wahi, Adv.

Ms. K.Enatoli Sema, Adv.

UPON hearing counsel the Court made the following O R D E R

Heard learned counsel for the parties.

We find no merit in the special leave petitions. The Special Leave Petitions are dismissed. However, we direct that there will be no disconnection to the petitioners electric supply till 30th June, 2009.

(Parveen Kr. Chawla) Court Master

(S.S.R.Krishna) Court Master

### **ANNEXURE - K**

99/09/2094

Chairman

TWT115 NO-

ANNEXUREJ

શિવલાલભાઈ એલ. બારસીયા C/O રાજકોટ એન્જી. એસોસીયેશન ભક્તિનગર ઈન્ડસ્ટ્રીયલ એસ્ટેટ, રાજકોટ

મિત શ્રી, અધ્યક્ષશ્રી, ગુજરાત ઈલેક્ટ્રીસીટી રેગ્યુલેટર કમીશન, ગાંધીનગર.

વિષય : રાજ્ય સલાહકાર સમીતી ૨૦૧૫ ના સુચનો બાબત ટાયુટ-સંદર્ભ : આપનો પત્ર નં : વહટ/રાજ્ય સલાહકાર સમિતિ / એજન્ડા / ૨૦૧૫ / ૦૦૭૬ તા.૧૨.૦૧.૨૦૧૫

Adm

સાહેબશ્રી,

જય ભારત સાથ જણાવવાનું કે, ઉપરોક્ત સંદર્ભથી મીટીંગ અંગે આપ સાહેબનો પત્ર મળેલ છે, જેમાં નીચેના મુદ્દાઓ આ સાથે સામેલ છે.

૧. જીઈઆરસી દ્વારા પત્ર નં. ૧૬૩૪ તા. ૦૨.૦૮.૨૦૧૪ માં ઓર્ડરમાં એક જ પ્રીમાઈસીસમાં સર્વિસ બદલ્યા વગર મીટર પોઝીશનમાં ફેરફાર કરવા માંટે ચાર્જીસ નક્કી કરેલ છે. જે ખરેખર ખૂબજ વધારે છે, અને તેમાં આવા ચાર્જીસ વધારાની દરખાસ્ત વખતે સલાહકાર સભ્યશ્રી / ગ્રાહકોના અભીપ્રાય લેવા ખૂબ જ જરૂરી છે.

 વખતો વખત કોઈપણ ડીસ્કોમ દ્વારા આવા કોઈ પણ ભાવવધારા પાછળથી રજુઆત કરી વધારો કરાવે છે, ગાહકોને અન્યાય તથા રજુઆત કમિશન તરફથી ધ્યાને લેવામાં આવતી નથી જે ખુબ જ દુખદ બાબત છે. એક વખત ફીક્સ થયેલ ચાર્જીસ ડીસ્કોમ રજુઆત કરીને સુધારો કરાવે જયારે તે ટેરીફમાં ગાહકને અન્યાય બાબત કમિશન તથા ડીસ્કોમ કોઈપણ નિર્ણય સમય થતો નથી (GERC/Tech/2014-1378 Dt.24-6-14)

 સી.જી.આર.એફ ઢારા અરજદારની દલીલોની નોંધ ઓર્ડરમાં લેવામાં આવતી નથી અને અનેકવાર પત્રો લખવા છતા કોઈપણ પ્રકારનો પ્રત્યુત્તર આપવામાં આવતો નથી.

૪. ડીસ્કોમ દ્વારા આપવામાં આવતી સર્વિસ વાયર માંગેલ લોડ મુજબની ક્ષમતા તેમજ ગુણવતા ન હોય ડીસ્કોમ દ્વારા વપરાતા સર્વિસ વાયરની ગુણવત્તાની તપાસ ડીસ્કોમ સિવાયની એજન્સી દ્વારા થવી જરૂરી છે. જેથી ગ્રાહકને સારી સર્વિસ મળી શકે.

 શપ્લાય કોડ રીવ્યુ પેનલમાં અન્ય વિસ્તારના ચેમ્બર ઓફ કોમર્સ તથા ઔદ્યૌર્ગ ક સંગઠનોને સ્થાન આપવા વિચારણા કરવી જરૂરી છે.

દ. હાલ જીઈઆરસી ના નોટીફીકેશન ૧૦ પ્રમાશે નવા કનેક્શન તેમજ લોડવધારા અંગેની કાર્યવાહી સમય મર્યાદામાં થતી નથી અને સમય મર્યાદામાં છુટ મેળવવા માટે અરજીઓ સ્વીકારવામાં એનકેન પ્રકારેના વાંધાઓ અને સમય આપીને આ પ્રક્રીયામાં આશરે ૧૫ દિવસ જેટલો સમય લેવામાં આવે છે. જે યોગ્ય નથી અને અંદાજપત્ર ભરાયા પછી પણ ઘણા કનેક્શનોમાં લાઈનકામ તથા કનેક્શન આપવાની પ્રક્રીયા આશરે બે માસથી વધારે સમયમાં થતી નથી જે યોગ્ય કરવું.

૭. ૧૧ કે.વી ઈન્ડસ્ટ્રીયલ ફીડરના ટ્રીપીંગ એક માસમાં ૧૫ વખતથી વધુ જાણ વિના ફીડર બંધ અને એક જ દિવસમાં ત્રણથી વધુ વખત ટ્રીપીંગ થતા ફીડરોની અલગથી યાદી બનાવીને તે ટ્રીપીંગ ઓછા થાય તે બાબતે કાર્યવહી કરવી અને તેની સમીક્ષા એડવાઈઝરીમાં યાહીતી આપવી અને તેની સુધારણા અંગે ચર્ચા કરવી અને ઓવરલોડ લાઈનને અંડર ગ્રાઉન્ડ કેબલ એરીયલ બન્ચ કેબલથી ટ્રીપીંગની સંખ્યા ઘટાડવા કાર્યવાહી કરવી.

સબસ્ટેશનમં વી.સી.બી. પેનલ તથા ડી.પી. ખર્ચ પણ સંપૂર્ણ પણે ગ્રાહક પાસેથી વસુલ કરવામાં આવે છે. અને સાથે સાથે આ ગ્રાહકોના અંદાજપત્રમાં ડેવલપમેન્ટ ચાર્જની ૨કમ વસુલવામાં આવે છે. આમ ગ્રાહક બે રીતે દંડાય છે, જે ચર્ચા કરીને સ્પષ્ટતા કરવી ખૂબ જ જરૂરી છે.

ઉપરોક્ત મુદ્દાઓ અંગે આગામી મીટીંગમાં ચર્ચા કરવા તથા યોગ્ય નિર્ણય થાય તેવી અપેક્ષા સાથે તેમજ આ સિવાય મીટીંગ દરમ્યાન અન્ય મુદ્દાઓ રજુ કરવા માંટે સમય ફાળવવા યોગ્ય કરશો. આભાર સહ…

Shived & Babasia)

# Shivlal L. Patel

Office: Sahyog Electric Works, Om Complex, Anand Banglow Chowk, Mavdi Plot Main Road Rajkot – 360 004. Ph: 0281-2386127, Mob No. 98250 79022

Date

२६.०१.२०१५

Past President of Vali Mandal

President

Rajkot Electric LicenseContractor Association
Rajkot.

M.G & S.G Bardanwala Kanya Vidhyalay, Rajkot

> ♦ Hon. Secretary

Rajkot Chamber of Commerce & Industry, Rajkot

Hon. Secretary

Rajnagar Co. Op. Housing Society Ltd, Rajkot

Trustee

Shree Khodaidham Trust Kagvad

Committee Member

Gujarat State Advisory Gujarat Electricity Regulatory Commission (GERC) Ahmedabad.

Gujarat Vijali Contractor Mandal, Ahmedabad

Saurashtra Electric Merchant Association, Rajkot

Shree Jankalyan Trust, Reg no. E-7010/13-2-2003, Rajkot

Gundasara Education & Charitable Trust પ્રતી શ્રી, અધ્યક્ષશ્રી, ગુજરાત ઈલેક્ટ્રીસીટી રેગ્યલેટરી કમીશન, ગાંધીનગર


વિષય: અમોએ અગાઉ કરેલ રજુઆતમાં ઉમેરવા બાબત

સાહબિશ્રી,

જય ભારત સાથ જણાવવાનુ કે અમોએ ૧૭.૦૧.૨૦૧૫ના રોજ આગામી ફેબ્રુઆરીની સલાહકાર બોર્ડની મીટીંગમાં રજુઆત કરેલ છે. જેના આ બે મુદ્દા ઉમેરવા વિનંતી છે.

- શહેર વિભાગમાં ફેક્ટરી કે કોમર્શીયલ અથવા ઓફીસ બિલ્ડીગમાં જગ્યાના અભાવે ૧૦૦ કી.વો. ના બદલે ૧૫૦ કી.વો. સુધી એલ.ટી કનેક્શન આપવા અંગે ચર્ચા કરવા વિનંતી છે.
- ર. સી.ટી.પી.ટી યુનીટની જગ્યા અંને માપ સાઈઝને સ્ટાન્ડર્ડ નક્કી કરવા બાબત.

### ANNEXURE - L



## **ANNEXURE - M**



#### **CONSUMER EDUCATION AND RESEARCH SOCIETY (CERS)**

SURAKSHA SANKOOL', THALTEJ, SARKHEJ-GANDHINAGAR HIGHWAY, AHMEDABAD-380 054, INDIA Phone: 27489945-46, 30121001-2-3, Fax: 079-27489947 Email: <a href="mailto:cerc@cercindia.org">cerc@cercindia.org</a>, Website: <a href="mailto:www.cercindia.org">www.cercindia.org</a>

To : Secretary, GERC, Gandhinagar

From K K Bajaj, Chief General Manager (Hon), CERS, Ahmedabad

Date:19.1.2015 Fax No: 23602054/23602055

Ref: Energy/KKB/2014\gerc/FAX/8

#### Sub: Agenda Points for State Advisory Committee Meeting

Dear Sir.

Consumer Education and Research Society would like to send following Agenda Points to be included and discussed in 21<sup>st</sup> State Advisory Committee meeting to be held in February 2015.

#### Agenda Points:-

- 1. Non-availability of gas for Power Plants.
  - 2. Poor Plant Load Factor of Generation Companies
  - Lack of confidence of consumers in CGRFs
  - 4. Violation of Regulations by DISCOMs
  - 5. Sealing of FPPPA charges at Rs.1.80/Unit
  - Reduction in Fees & Charges by GERC
  - 7. Distribution of LED lamps by DISCOMs
  - 8. Request to Govt. for reduction in Electricity Duty
  - 9. Repeated absence of SAC Members
  - 10. Tariff hearing to be held at different locations.

We would request you to include above points for forthcoming SAC meeting.

Thanking you,

Yours faithfully,

Sd/-

K.K. Bajaj

Chief General Manager (Hon.)



॥ कृषिमित् कृषस्य ॥

## किसान संघ



नोधणी नं. गुज/337 रजी. नं. एफ /330/महेसाणा

कार्यालयः बलराम मंदिर परिसर, कलेकटर ओफिस के सामने, घ-रोड, सेकटर-१२ डी, गांधीनगर फोन: (079) 23221976 टेली फेक्स: 23224916 E-mail @ bksgujarat.org.in www.bksgujarat.org.in

क्रमांक :

પ્રતિ, અધ્યક્ષશ્રી, ગુજરાત ઈલેક્ટ્રીસીટી રેગ્યુલેટર કમીશન, ગાંધીનગર. તા. ૦૫/૦૩/૨૦૧૫

9MAR 2015

વિષય :- <u>રાજય સલાહકાર સમીતી ૨૦૧૫ના સૂચનો બાબત.</u>

(૧) કંપનીઓ ઘ્વારા થ્રી ફ્રેઈજ ખેતીવાડી મીટરો ગ્રાહકોને આપવામાં આવે છે તે મીટર કોઈપણ ફોલ્ટ કે ટેકનીકલી ફોલ્ટ નીકળે કે બંધ પડી જાય તેવા સંજોગોમાં ગ્રાહકો પાસેથી જ નાણાં ભરાવવાનો આગ્રહ રાખવામાં આવે છે.પરંતુ માહિતીનુસાર મીટર સપ્લાય કરતી કંપની સાથે થયેલ શરતો મુજબ જો ગેરંટેડ પિરીયડમાં ફોલ્ટ થાય તો કંપની પાસેથી વસુલવાનો આગ્રહ રાખવો તેવી ક્ષેત્રીય કચેરીઓને સૂચના આપવી.

(૨) ખેતરમાં નવા સીંગલ ફેઈઝ વીજ જોડાણ માટે (ફાર્મ હાઉસ કે ખેતરમાં) લેવા માટે હાલ નવીન પરીપત્ર—તમામ કંપનીઓ ઘ્વારા પરીપત્ર કરીને ઓછામાં ઓછા ૧ લાખ રૂા.લેવાનો પરીપત્ર કરેલ છે. જે તેના અંતર કે મટીરીયલ્સ એસ્ટીમેટ મુજબ થતા નાણા

લઈને આપવા જોઈએ.

(૩) વીજચોરીમાં ૧૩૫ની કલમનો દૂર ઉપયોગ કરીને ખેડૂતોને પરેશાન કરનાર અધિકારી પર કાનુની કાર્યવાહી કરવી.

(૪) કનેકશન આપવા બાબતે ટાઈમ બાઉન્ડ કામ ન કરનાર અધિકારી પર એકશન લેવા.

(પ) ટ્રાન્સફરમર બળી ગયા પછી યુનિસીયલ ફેલ ટીસી બેસાડવામાં આવે છે.

(૬) શીફ્ટીંગના નિયમો સરળ બનાવવા.

(૭) પરિપત્રો ગુજરાતીમાં કરવા.

(૮) સમયસર ગ્રાહકોને સર્વિસ આપવા સ્ટાફની અછત હોયતો સત્વરે ભરતી કરવી અથવા

તો કોન્ટ્રાકટરો પાસેથી સમયસર કામ લેવું.

(૯) શીફ્ટીંગ અને તત્કાળ યોજનામાં કંપનીના માન્ય તમામ મટીરીયલ (પોલ, કંડકટર, ટ્રાન્સફોરમર, વિગેરે) બજારમાંથી ખરીદીને કોન્ટ્રાકટર ઘ્વારા લાઈનો ઉભી કરાવી શકે જેથી નાણાં અને સમયની બચત થશે અને માલની ગુણવત્તા જળવાશે.

ભવદીય, બગુજભાઈ પૃદેધ (મગનભાઈ પટેલ) પ્રદેશ અધ્યક્ષ

## **ANNEXURE- O**

TWDWS NO-



Office of the Chief Electrical Engineer Station Building, 5<sup>th</sup> floor. Churchgate, Mumbai-400020.

Email- dycaetrdwr@yahoo.co.in

Date: 20.03.2015

No. EL 84/17(GEB) Vol. IX
Gujarat Electricity Regulatory Commission
6th floor, Gift One, Road -5 C, Zone-5
Gandhinagar- 382355

Sub: Agenda Items of Western Railway(Traction) for the proposed meeting of 21st "State Advisory Committee "of GERC.

Ref: Ref: Your letter no.GERC/VHT/21st SAC/2015/322 dt.12.02.15.

Western Railway is very thankful to Hon'ble GERC for regularly arranging "State

Advisory Committee" meetings, where State Advisory Committee members are given a

chance to discuss different policy matters which are very fruitful. Western Railway would like to
submit following Agenda for discussion in above meeting and for kind consideration of
Honourable GERC.

- (i) Failure of Transmission lines feeding to Traction Sub-stations. Annexure-Al & All.
- (ii) Pending defects & deficiencies not attended by GETCO Annexure B.
- (iii) Maintenance of power line crossings to Railway track Annexure C.

Modifying over head power line crossings upto 33KV to under ground cable.
 Details are enclosed as Annexure-D.

Thanking You,

DA- As above

Admi

CHIZ

Chairman

(Bril Rai )

Dy. Chief Electrical Engineer (Traction Distribution)
For Chief Electrical Engineer

Copy to-

The Managing Director, Gujarat Electric Transmission Co. Sardar Patel Vidyut Bhavan, Vadodara, It is requested to take up the matter with concern official for maintenance of Power line crossing, attending defects/deficiencies and remedial measures for Power line failures, feeding to Riy Traction sub stations.

Annexure

## 1.0 Grid Supply Failure feeding to Rly Traction Sub-stations.

Grid supply failures from GSS at Atul, Songarh, Mota, Ode & Vilayat are high. Details are as follows.

Name of	Supply	201	3-14	2014-upto	16 Mar15.
TSS	from GSS	No of incidences of supply failure	Total supply failure in hrs & minute	No of incidences of supply failure	Total supply failure in hrs & minute
ATUL	ATUL .	9	1'07"	8	4'45"
Bhestan	Bhestan	2	36"	4	1'13"
Navapur	Songarh	16	17'59"	7	1'52"
Control of the Contro	Mota	5	18'05"	2	1'14"
Madhi		8	1'22"	8	15'56"
Anand	Ode	1	33"	6.	11'44"
VAGRA	Vilayat	41	39'42"	35	36'44"
Total		41	33 42		

GETCO may be directed to ensure the uninterrupted power supply to Railways because interruption in power supply affects punctuality of trains and cause inconveniences to general public. Details of Supply failures reported during Yr. 2013-14 & Yr. 2014-15 (up to 16 Mar 15) are enclosed here with as Annexure-Al & All.

## 1.1 Pending defects & deficiencies not attened -

During the joint inspections by Rly & GETCO several Defects/ Deficiencies are noticed. However these are not attended on priority. List of such Defects/ Deficiencies noticed during joint survey during Yr. 2014 have not yet been attended is enclosed here with as Annexure-B

## 1.2 Maintenance of Power Line Crossings to Rly Track-

Details of Power line crossing maintenance are not known to Rly. The details of the Power blocks demanded from the Rly by the GETCO / DGVCL / MGVCL in order to carry out the maintenance work have been enclosed as Annexure-C. It is seen that most of Transmission line crossingmaintenance is lapsing.

# 1.3 Provision of under ground cables in place of 11KV/ 33KV Power Line Crossings to Riy Track-

In view of Power Line Crossing regulations 1987 and A&C slip no.18 issued by Rly Bd issued vide lette no. 2000/Elect(G)/161/1 Pt. III dt 19.01.09 overhead line crossings up to 33KV shall be under ground type.From the enclosed data (Annex-D) it can be noted that 13 nos of 11KV & 04 NOS OF 33KV power line crossings are over head type. It shall be appreciated that converting of these power line crossings to under ground will be in the mutual interest of Rly & DISCOMs for better safety and reliability requirements. Rly request that DISCOMs may be directed to modify these crossings at their cost, being owner of the crossings. Rly will extend all support in getting drawings approved and execution of the work.

Annexure - A I

## TRACTION POWER SUPPLY FAILURE FOR THE YEAR 2013-14

N TSS SEB	TSS	SEB	Incoming Supply	Date	Time of s failu		Duration	Remarks
,	100	-	Voltage		From	To		
-	-				20.42	20.47	0.05	Tower no.116 R phase insulator broken
				13.04.13	21.09	21.20	0.11	Control of the Contro
				31.05.13	9.50	9.56	0.06	Line tripped during meter testing
				01.00.10	12.03	12.09	0.06	Supply failed from NVS/GSS
	1		XXXXXXXXX	30.08.13	12.16	12.22	0.06	Y phase EFR operated at ATL/GSS
1	ATUL	GEB	132 KV	09.09.13	8.59	9.16	C.17	Jumper broken at VAPI/GSS
				09.00.10	9.20	9 25	0.05	Tree branches touching 132 KV NVS
- 1			1	23.09.13	12.06	12.15	0.09	ATL line at Tower nos.54 & 55
				03.03.14	17.39	17.41	0.02	Tripped from ATUL/GSS while working on control panel
-	14		7-1-1	-		1 - 1 - 1	.1'07"	- X
			Total	50.00.40	12.03	12.21	0.18	Supply failed from NVS/GSS
			420.60	30.08 13	12.03	55363.02		NVS-BHET 132 KV line tripped from
2	BHET	GEB	132 KV	11.03.14	16.09	16.27	0.18	NVS due to metallic yarn on tower
	10.00		Total				0.36	
				28.04.13	4.47	4.50	0.03	EFR operated
3					7.54	7.59	0.05	EFR operated at MOTA GEB
				07.06.13	9.24	9.29	0.05	Er it operates at mo in occ
3	MID	GEB	66 KV	14.09.13	18.10	18.32	0.22	EFR operated at MOTA GSS
				11.11.13	19.40	13.10	17.30	Y phase jumper melted on tower no.2 & EFR operated at GEB MOTA
			Total				18'.05"	
				02.05.13	1.31	1.48	0.17	OCR in R phase operated in Hydro stn
				02.05.15	1,01		-	220 KV TPH Tie line B phase main bu
				12.05.13	12.33	13.20	0.47	bar isolator suspension disc flashed
				05.06.13	6.50	7.50	1.00	LA burst at GEB/USD hydro power pla
				06.06.13	16.53	16.58	0.05	EFR operated at USD/GEB due heavy storm/rain
				06.07.13	13.15	13.38	0.23	EFR operated at USD/GEB due heavy storm/rain
				08.07.13	4.34	4.45	0.11	EFR operated at USD/GEB due heavy storm/rain
				11/12.8.13	17.56	3.30	9 34	EFR operated at USD/GEB due to phase jumper broken at tower no.38
				11.09.13	18,10	18.32	0.22	EFR & OCR operated at USD/GSS
4	NWU	GEB	66 KV	14.09.13	16.25	16.34	0.09	nydro supply (hipped at ooc
				17.09.13	4.26	4.52	0.26	Fdr. II hydro supply tripped at USD of to heavy rain & lightening
				11.11.13	16.45	19.59	3.14	EFR operated at GEB/USD
				06,12.13				Ukai hydro R phase OCR operated
	*			12.01.14		18.00	0.15	Ikai hydro R phase tripped OCR & E
				14,01.14	1	6.15	0.1	Ukai hydro R phase tripped OCR & E operated at USD-VYA line
				21.01.14	21.57	22.15	0.18	I lkai hydro R phase tripped OCR & E
				28.01.14	6.55	7.35	0,4	Air pressure of circuit breaker drop
			_		-		17"5	

		050	Incoming Supply	Date	Time of failu		Duration	Remarks
5N	TSS	SEB	Voltage	Date	From	T.o '		
				02.04.13	16.53	16.55	0.02	OCR operated
	1 20 1	-	100101	28.09.13	1.29	1.33	0.04	Halcarwa feeder tripped on OCR
5	BH	GEB	132 KV	22.01.14	2.49	3.05	0.16	Feeder no.1 tripped on earth fault
			1	01.03.14	3.29	3.50	0.21	Haldarwa feeder tripped on earth fault
	6 0		Total				0.43	
6	MPR	GEB	132 KV	02.05.13	10.36	10.55	0.19	03 parallel fransformers tripped
						00.00	0.40	GEB feeder no.2 tripped on earth fault
				11.07.13	22.50	23.32	0.42	GEB feeder no.2 tripped on earth fault
			1 0	25.07.13	14.08	14.11	0.03	Karamsad feeder tripped on earth faul
				07.09.13	18.08	18.17	0.09	Karamsad feeder tripped on earth faul
7	ANND	GEB	132 KV	02.10.13	10.11	10.22	0.11	Karamsad feeder tripped on earth faul
	7314136	, out	1	23.10.13	11.37	11.4	0.03	Karamsad feeder tripped on earth faul
				29.10.13	10.03	16.33	0.05	Feeder no.1 tripped on earth fault
				29.12.13	16.27		0.05	Karamsad bus coupler problem
				07.03.14	12.06	12 31	1'22"	Raisinsad bus coopici problem
			Total	40.00.40	10.13	10.38	0.25	Bus tripped on earth fault due to rain
	1	1		10.06.13	12.13	12.20	0.07	Feeder tripped on earth fault
		1	-	27.08.13	11.47	12.02	0.15	VTA feeder tripped on earth fault
8	MHD	GEB	132 KV	31.08.13	1.48	1.58	0.13	VTA feeder tripped on earth fault
0	WIND	GCD	102.11	03.10.13	1.48	2.09	0.21	VTA feeder tripped on earth fault
					12.32	12.37	0.05	
				14.01.14	15.17	15.22	0.05	Feeder no 1 tripped on earth fault
			Total				1 28"	
	1			20.12.13	6.55	7.23	0.28	GDA feeder no 1 tripped on earth fau
			11	21,12,13	6.13	6 23	0.1	GDA feeder no 1 tripped on earth fau
9	GDA	GEB	132 KV	05.01.14	8.15	8.20	0.05	GDA feeder no.1 tripped on earth fau
				11.01.14	5.26	5.27	0.01	GDA feeder no.1 tripped on earth fau
				09.02.14	7.42	7.50	0.08	GDA feeder no 1 tripped on earth fau
			Total				0.52	
10	VGR	GEB	220 KV	05.09.13	0.45	1.18	0.33	Haldarwa feeder tripped on earth fau

Annexure - A II

TRACTION POWER SUPPLY FAILURES (APR-14 TO MAR 15).

	TOO	CER	Incoming	Date	Time of	supply	Duration	Remarks
IN	TSS	SEB	Supply	Date	From	To	Duration	
-			ouppij		3.13	3.25	0.12	
		- 1		11.06.14	3.37	4.17	0.40	NVS-ATL line jumper burnt at tower no.122
		-			4.37	5.44	1.07	
		- 1			2.12	2.19	0.07	132 KV line tripped at NVS due to heavy rain
				· · · ·	2.12	2.10		Tree fallen on Tx-line between tower nos. 98 &
		1		19.07.14	8.21	8.30	0.09	99. Conductor with insulator detached from
					0.21	0.50	0.00	support at tower no.97.
1	ATUL	GEB	132 KV					132 KV GEB R-Y phase tripped due to peacock
				30.09.14	15.56	16.11	0.15	
	- 1	- 1		00.00.11				electrocution.
	1			L	14.41	14.50	1.09	132 KV GEB R-Y phase tripped on OCR.
	1	- 1		04.10.14	15.39	15.45	1.06	Mango tree branch fallen & came in the zone o
	1				10.00	10.40	1.00	Tower nos 53-54.
		1		Total			4.45	
					44.50	15.19	0.27	Inter phase short circuit at NVS/GSS due to
	4			21.04.14	14.52	15.19	0.27	storm
		1		02.05.14	16.21	16.25	0.04	BHET/GEB tripped with EFR
2	BHET!	GER.	132 KV	05.05.14	12 21	12.47	0.26	BHET/GEB fdr.!! tripped with OCR & EFR
4	DI.E.		10210					NVS-BHET feeder - 2 tripped from NVS &
		7		30.05.14	11.31	11.47	0.16	feeder - 1 was under outage
		9					1.13	
				Total			1.13	EFR operated & earth screen wire broke
				20/21.4.14	22.14	1.05	1.09	between tower nos. 28 & 29 at MOTA/GSS
	1 3		100-00000	20,0				66 KV supply failed due to EFR operated o
3	MID	GEB	66 KV	07.02.14	18.47	18.52	0.05	
	100000		- Re-	07.02.14	10.47	10.02	-	Rly. feeder.
				Total			1.14	
				26.03.14	9.48	10.12	0.24	EFR operated at USD hydro power plant
	- 1	9		09.04.14	21.17	21.20	0.03	EFR operated at GEB/USD
		N 9		10.06.14	21.51	22.24	0.33	EFR & OCR operated at USD Hydro Station
	1730,600,8	Carreno S		11.06.14	2.30	2.37	0.07	EFR & OCR operated at USD Hydro Station
4	NWU	GEB	66 KV	13.09.14	10.05	10.20	0.15	EFR operated at UKAI Hydro Station.
	otomicon.			09.10.14	12.30	12.40	0.10	OCR & EFR operated at GEB USD.
				The second secon	23.17	23.46	0.29	OCR operated at GEB USD.
				12.03.15	20.17	25.45	1.52	O D T T T T T T T T T T T T T T T T T T
				Total	24.04	11.35	14.34	Karamsad both feeders tripped on earth fault
				10.05.14	21.01		0.18	Karamsad both feeders tripped on earth fault
				11.05.14	13.21	13.39		Karamsad built teecers tripped of cartification
	1	(14)		06.08.14	00.43	00.54	0.11	Karamsad-ODE line tripped on earth fault
		0	1	11.09.14	18.30	18.34	0.04	Karamsad-ODE line tripped on earth fault
				11.09.14	18.39	18.57	0.18	Both feeders tripped at Karamsad-OD line du
U	ANND	GEB	132 KV	15.09.14	9.50	9.56	0.06	
				15.05.14	1,806,088	31,000,000		to earth fault (Y-phase).
				13.10.14	22.05	22.22	0.17	R-phase tripped on EFR operation
	1	1	i	1404444	11.50	1 11.58	0.08	132 KV Karamuad - ODE both feeders trippe
	1		1	18.11:14	.11.50	11.50	0.00	on EFR.
				Total			15.56	
_	-	-	1	06.07.14	6.02	7.30	1.28	
		1		10.07.14	6.15	7.20	1.05	
		1			3.22	3.49	0.27	Tripped on earth fault as porcelain insulat
			200101	11.07.14		6.22	1.50	flashed in saline area
6	VGR	GEB	220 KV		4.32	5.44	2.04	
				13.07.14	3.40		4.50	
					6.48	11.38	11.44	
				Total			11.44	132 KV GDA-DHD feeder R-phase tripped w
-	DUE	000	132 KV	20.04.14	20.01	20.16	0.15	master trip relay due to bad weather
7	DHD	GEB	132 KV	20.04.14			7000	MHD-ND GEB side both feeders tripped
			400 101	42 40 14	12.42	12.51	0.09	
8	MHD	GEB	132 KV	13.10.14	12.42	12.01		EFR operated.
	BMI	GEB	132 KV	13.11.14	14.22	14.40	0.18	MPEB side DPR operated.



Annexure- B

					WESTER	N RAILWAY		
			Details	of Defect	and Deficie	ncies of Po	wer line crossings.	
N	Div	Section	Between Stns	Trans Line Voltage in KV	Owned by	Date of Last Joint Inspection	Any Defect/defecincles observed	Whether Attended (Y/N)
1			SJN-BLD	66	GETCO	13.5.14	Earthing of tower are hidden.	N
-		VR-ST	SJN-BLD	11	DGVCL	27.5.14	Earthing is not proper .     Tower are rusty	N
			VAPI-BAGD	11	DGVCL	5.5.14	one lacing of guard wire ( west side south end ) broken.	Attended o 11.09.14
	+	UDN-JL	BHET-NICL	66	GETCO	24.4.14	Line dead	N
i	1	ODIT-SE	SCH-BHET	132	GETCO	24.4.14	Fitting rusted on both end.	N
ì			SCH-BHET	132	GETCO	24,4,14	Fitting rusted on both end.	N
7	BL		SCH-BHET	66	GETCO	24.4.14	Tower legs rusty.	N
8	DL	VR-ST	BHET-UDN	66	GETCO	24.4.14	Fitting rusted on both end, Line dead	N
9			UDN-ST	66	GETCO	24.4.14	Earthing not provided & line dead	N
10			CHM-GGAR	66	GETCO	24.4.14	Line dead.	N
11			BHET-NIOL		GETCO	24.4.14	Line dead.	N
12		UDN-JL	TPH-USD	11	DGVCL	14.5.14	Earthings are broken.     Anti-climbing device not available.	N
13		ODIVAC	TPH-USD	11	DGVCL	14.5.14	Earthings are broken.     Anti-climbing device not available.	N
14			URN-ST	56	GETCO	23.01.14	Earth wire not available. Dead line	N
15			KSE-G1X	220	PGCIL	11.04.14	Two seperate and distinct earth electrode to be provided Anti climbing device and warning board are rusty.	N
16	1		KSE-GTX	66	GETCO	28.01.14	Earth electrode not available, 1 disc	N
17	-		KSE-GTX	220	TORRENT	C4.03.14	Two seperate and distinct earth electrode to be provided.	
18			GTX-SYN	220	GETCO	05.04.14	Two separate and distinct earth electrode to	N
15			GTX-SYN	66	GETCO	28.01.14	Earth Electrode are not available.	N
20	BRC	ST-BRC	SYN-KIM	11	DGVCL	05.04.14	provided.	
2			KIM-KS6	220	GETCO	05.04.14	Two separate and distinct earth electode to be provided. Earth wire not available.Anti climbing assembly and warning board are rusty.	N
2	2		KIM-KSB	66	GETCO	05.04.14	and warning board are rusty	N
2	3		KIM-KSE	3 220	PGCIL	. 11.04.1	Two seperate and distinct earth electode to be provided. Earth wire not aviiable. Anti- climbing device and warning board are rusty.	O N

S N	Div	Section	Between Stns	Trans Line Voltage in KV	Owned by	Date of Last Joint Inspection	Any Defect/defecincies observed	Whether Attended (Y/N)
24			KIM-KSB	66	GETCO	05.04.14	Two seperate and distinct earth electrode to be provided. Hardware and fittings of conductor are coroded. Anti climbing device and warning board are rusty	N
25			AKV BH	400	ESSAR	18.02.14	Two seperate and distinct earth to be provided on each tower	N
26			CAŻ-NIA	400	PGCIL	C2.04.14	Two separate and disclinct earth electrode to be provided. Anti-climbing device and warning notice board to be provided.	N
27			CVJ-NIU	220	GETCO	10.02.14	Anti-climbing device of both tower are rusty and broken, warning and notice board are not available	· N
28			CVJ-NIU	220	GETCO	10.02.14	Anti climbing device of tower No. 28 are rusty and broken.barbed wire of anti climbing device is missing	N
29		-	VRE-PLJ	66	GETCO	10.02.14	R phase one no. disc insulator half disc broken. Anti climbing device and warning notice board are rusty and broken.	Attended on 08.12.14
30		ST-BRC	PLJ-LKD	400	PGCIL	19.05.14	Two separate and distinct earth electrode to be provided	N
31			PLJ-LKD	400	TORRENT	19.02.14	Separate earth electrode not avilaible. Barbed wire of anti climbing device are	N
32			PLJ-LKD	220	GETCO	10.02.14	Two seperate and distinct earth not grovided.	N
33			PLJ-LKD	220	GETCO	19.02.14	Earth wire on crossing span not avilable. Anti climbing device and warning board are rusty.	Attended on 28.01.15
34	BRC		LKD-MYG	220	GETCO	17 02.14	Existing earth stations broken. Two separate and distinct earth on each tower to be provided. Anti-climbing device and barbed wire of both tower missing.	N
35			LKD-MYG	66	GETCO	17.02.14	Anti climbing device and warning board are rusty	N
36			MYG-KSPR	68	GETCO	17.02.14	Anti climbing device and warning board are rusty.	N
37			MPR-VS	68	GETCO	28.04.14	Earthing is not visible as it is under ground.	N
38			MPR-VS	66	GETCO	28.04.14	Earthing is not visible as it is under ground.	N
39			BJW-RNO	132	GETÇO	14.05.14	Earth conductor to be provided.	N
40			BJW-RNO	132	GETCO	14.05.14	Earth conductor not avilable. To be provided.	Attended on 20.11.14
41			BJW-RNO	132	GETCO	14.05.14	2 Nos. joint clamp in bottom conductor	N
42	1		BJW-RNO	132	GETCO	14.05.14	2 Nos. joint clamp in bottom conductor	N
43			RNO-VDA	132	GETCO	14.05.14	Earth conductor not available, to be provided.	N
44		BRC-ADI	VXD-ANND	11	MGVCL	08.08.14	Safety net provided below the over head	Attended or date 26-05- 13 and maint. done.
45	1		KBRV-UTD	11	MGVCL	21.02.14	Safety net wire found broken. Structures require painting.	N
46			KBRV-UTD	11	MGVCL	21.02.14	Proper anti-climbing devices are not	N

(6)

N	Div	Section	Between Stns	Trans Line Voltage in KV	Owned by	Date of Last Joint Inspection	Any Defect/defecincies observed	Whether Attended (Y/N)
47	-		KBRV-UTD	11	MGVCL	21.02.14	One foundation of east side pole found broken.Structures require painting.	N
48		BRC-ADI	ND-GTE	11	MGVCL		Two strands of one phase wire and one	The same has been attended.
49			GTE-MHD	-11	MGVCL	08.05.14	Structure require painting.	N
50			SVL-WTPS	220	GETCO	30.01.14	Anti climbing device not available	N
51			SVL-TBA	11	MGVCL	28.03.14	Proper anti-climbing devices are not provided. Warning boards are faded and structures require painting.	N
52		ANND-GDA	TWA-VKG	56	GETCO	30.01.14	Warning notice plate not available	N
53			TWA-VKG	220	GETCO	30.01.14	Anti climbing device not available	N
54	1		VKG-GDA	132	GETCO	30.01.14	Anti climbing device not available	N
55	1		GDA-KRSA	132	GETCO	30.01.14	Anti climbing device not available -	N
56	1	BRC-GDA	GDA-KRSA	66	GETCO	30.01.14	Anti climbing device not available	N
57	-		BRC D-PIO	132	GETCO	25.03.14	14 2 Nos bulging/unwinding 7 strands on Y and B phase conductor	N
58	-		THAM-SAZ		GETCO	20.05.14	2 Nos bulging/unwinding 7 strands on Y and B phase conductor	N
59	BRC		THAM-SAZ		GETCO	30.05.14	Anticliming device, caution board not available	Attended on 21.08.14
60	-		THAM-SAZ		GETCO	30.05.14	Anticliming device, caution board not available	Attended on 21.08.14
61	-		VGR-SAZ		GETCO	20.05.14	Anticliming device, caution board not available, structure rusted	Attended on 20.08.14
62			VGR-PKJ		GETCO	26.04.14	3 Nos. bulging / unwinding 7 strands	Attended on 08.12.14
63	3	BH-DHF	VGR-PKJ	66	GETCO	26.04.14	Anti climbing device and coution board not	Attended on 20.08.14
6	4				GETCO	24.04.14	Anticlimbing device, caution board not	Attended or 20.08.14
6			VGR-PK	-	GETCO		Control of the Contro	Attended or 20.08.14
L	6		PKJ-DHF		GETCO	-	Both earth pits are damaged.	N
L	7		DHF	220	GETCO		Both earth pits are damaged.	N
-	18		GTX-KSI		TORREN		Two separat and district earth electrode to be provided.	N
L	9		GTX-KSI		GETCO	23.01.1		N
L	70	KBCS					Earth wire is missing and to be provided . 1 No stiffner angle broken,1 petticoat of disc insulator found broken Anti climbing device not available.	N.

S N	Div	Section	Between Stns	Trans Line Voltage in KV	Owned by	Date of Last Joint Inspection	Any Defect/defecincies observed	Whether Attended (Y/N)
71			ADI-GNC	66	GETCO	03.04.14	Guard wire provided. Line is dead, so needs to be removed	N
72	ADI	GER-GNC	ADI-GNC	66	GETCO	03.04.14	Guard wire provided. Line is dead, so needs to be removed	N
75			DHD-RET	33	GETCO	22.05.14	Tower of DN side stay wire found borken and remaing all other stay found loose should be tightended.	Attended
76			DHD-RET	33	GETCO	22.05.14	UP side 2 nos stay wire of tower found loose should be retension.	Attended
77	RTM	GDA-NAD	PPD-SAT	33	GETCO	24.05.14	On both tower creeping plant approaching near to charged area, it should be removed from pole.	Attended
78			LMK-MAM	33	GETCO	24.05.14	UP side 1/2 disc broken of both termination insulator.	Attended



					West	em Railway			- 033	10			
				Details of	Power lin	ne crossing M	aintenand	ce					
E	Div S	Section	Between Stations	Location	Trans Line Voltage in KV	Owned by	Date of maint	Time of	Power To	Remarks			
-	-+	-	VGN-DRD	114/3-3A	220	GETCO							
	1		SJN-BLD	158/3-4	66	GETCO				Shut Down not demanded by			
	- 1		SJN-3LD	159/25-26	11	DGVCL				SEB for maintenance work			
	- 3		KEB-VPI	167/11-12	220	GETCO		-					
	- 70		KEB-VPI	167/17-18	66	GETCO	44.00.44	13.25	13.55	Guard wire replaced.			
1			VPI-UVD	174/1.2	- 11	DGVCL	11.09.14	13.25	13.33	Grand with represent			
ľ			VPI-UVD	174/15-16	66	GETCO		+					
1			ATL-BL	193/9-10	66	GETCO		-					
1	1		AML-VDH	223/5-6	66	GETCO	-			1			
			NVS-VDH	234/13-14	66	GETCO				1			
			MRL-SCH	247/13-14	66	GETCO							
		VR-ST	MRL-SCH	247/29-30	220 66	GETCO							
			MRL-SCH	250/29-30	132	GETCO							
	1		SCH-BHET	254/9-10 254/31-32	132	GETCO		10000					
1		1	SCH-BHET	254/31-32	66	GETCO							
1	- 1	-	SCH-BHET	260/11-12	66	GETCO			1				
-	- 1	-	BHET-UDN	263/25-26	66	GETCO							
1	- 1	-	UDN-ST UDN-ST	264/7-8	66	GETCO							
4	1	-	BHET-NIOL	UB-1/17	66	GETCO				1			
1	- 1	-	BHET-NIOL	UB-2/7	66	GETCO				-			
+	BL	-	UDN-CHM	TV-17	66	GETCO		-	-	4			
-	DL		UDN-CHM	TV-7/9	66	GETCO		-	-	-			
1	-	_	CHM-GGAR	TV-12/5	66	GETCO			-	Shut Down not demanded b			
		- 1	CHM-GGAR	TV-12/6	220	GETCO		-	-	SEB for maintenance work			
	1		CHM-GGAR	14/8	66	GETCO	+	-	-				
1	- 1		CHM-GGAR	17/4	220	GETCO	-	+	1	1 1 1			
1	- 1		CHM-GGAR	18/8	220	GETCO		+	_	1			
	- 7		CHM-GGAR	18/9	220	GETCO GETCO				*			
			CHM-GGAR	18/14	66	GETCO		10					
		1	CHM-GGAR	18/16	400 66	GETCO							
			GGAR-BIY	22/8	220	GETCO	-						
1	0	UDN-JL	GGAR-BIY	24/9	400	GETCO	-						
			GGAR-BIY	24/12	66	GETCO							
	Q - 9		BIY-MID	41/6 52/12	220	GETCO							
5			MID-VYA MID-VYA	59/4	66	GETCO							
7		1	VYA-KKRD	62/6	66	GETCO							
3			USD	73/6	66	GETCO				-			
9			USD-TPS	GEB-3/7	66	GETCO			1	-			
1			USD-TPS	GEB-3/17		DGVCL	-	-					
2			USD-TPS	GEB-3/18		DGVCL	-		-	_			
3			USD-JAMKHADI			GETCO	-		-				
-			LMK-PPD	508/5-8	132	GETCO	+						
7			PPO-SAT	493/21-19		GETCO	1						
3			PPD-SAT	492/9-12		GETCO	1 78						
1	1	1	SAT-CCL	485/15-18	-	GETCO			-				
5	4	i	CCL-107	476/3-6	220	GETCO			1				
5	4	1 1 5	CCL-KIZ CCL-KIZ	475/11-12		GETCO							
7	4		KIZ-GDA	472/17-19		GETCO			-	Shut Down not demanded			
8	1	Santana Santa	PPD-SAT	491/23-26	33	MGVCL				SEB for maintenance wo			
9	RTM	GDA-NAD		517/31-34	_	MGVCL				OED IOI HIB ILEHORIOG NO			
0	1	1	LNK-MAM	537/23-25									
1	1		DHD-RET	537/28-30		GETCO							
12	1		DHD-RET	538/1	33	0.0000000000000000000000000000000000000	1		-	_			
	4		DHD-RET	538/17-18	33	MGVCL							
13	-	1		538/21-24	-	MGVCL							
14	-		DHD-RET	553/6-8		GETCO							
15	1	1.1	BIO-ANS	20.3/0-8	00	MGVCL	_	-	3				

-			-			Trans			Time of	Power	
1	Div	Se	ction	Between Stations	Location	Line /oltage in KV	Owned by	Date of maint	From	То	Remarks
	_	1	-	GER-VTA	486/13-15	132	GETCO	15.02.2014 16.02.2014			
1							GETCO	07.01.2014			
				GER-VTA	486/28-30	66	GETCO	10.10.2014		- 1	
1		1	-	V-100T	500/18-20	66	GETCO	16.01.2015			1 201
		1	-	ADI-SBT	500/18-20	56	GETCO	17.01.2015			
		1	-	ADI-SBT	IFF04/03-04	66	GETCO	17.01.2015			
1			-	SET-CLDY	505/1-3	66	GETCO	17.01.15			-
4			-	SBT-CLDY	.505/28-30	66	GETCO	17.01.2015		-	Maintenance activity e.g.
-			-	SBT-CLDY	505/30-32	66	GETCO	DEAD LINE			measurement of earth
-			1	SBT-CLDY	508/3-4	66	GETCO	17.01.2015			resistance, cleaning of insulator, tightening of jumper,
		1		SBT-CLDY	508/4-5	66	GETCO GETCO	16.01.2015		100	checking of jumper etc are
	ADI	GE	R-GNC	SBT-CLDY	509/13-14	66	GETCO	17.12.2014			carried out without Power block
	1	1	Ī	CLDY-KHD	514/7-8	68 66	GETCO	20.01.2015			from railway.
5	1	1		KHD-KALOL	IFF 5/13-14	66	GETCO	17.12.2014			
3				KHD-GNC	518/7-8 518/7-8	66	GETCO	10.11.2014		-	
7		1	1	KHD-GNC KHD-KALOL	IF 02/18-IF	66	GETCO	17,12,2014	1	-	
В	1				IF 02/18-IF		GETCO	10.11.2014	1	1	
9		1		KHD-KALOL	03/1	66	GETCO	23.04.201			
0				KHD-GNC	526/16-527/1	56			-	+	
_	4				IF 04/9-10	400	GETCO	28.11.201			
2	-		73		IF 04/9-10	400	GETCO	23.09.201	4	1	
1	1	1		URN-ST	268/27-29	66	GETCO	-	1	-	1 1 1
-	-	1		KSE-GTX	275/27-29	66	GETCO	_	-	-	
3	-	1		GTX-SYN	278/18-20	220	GETCO	-			
4	-			GTX-SYN	278/15-17	66	DGVCL	-			
5	-			SYN-KIM	287/15-17	11	GETCO	-			
6				KIM-KSB	293/16-20	220	GETCO				
7				KIM-KSB	294/23-25 295/7-9	66	GETCO				
8				PAO-AKV	309/5-7	66	GETCO				4
9	-	- 1		KBCS	KK-8/8-9	66	GETCO			+	
10				KBCS	KK-8/8-9	66	GETCO	and the same of th	-		
11	-	- 1		KBCS	KK-16/3-4	66	GETCO		-		
13	-			KBCS	KK-19/6-7	220	GETCO		1		
10				KBCS	KK-19/7-8	220	GETCO				
* 5	-			KBCS	KK-19/8-9	220	GETCO				
18	-	- 1		KBCS	KK-19/12-13	66	GETCO				
1				KBCS	KWS-1/4-5	- 00	GETCO				
13	_	1		KWS	KWS-1/4-5			3 1			
	9			KWS	25	66	GETC			-	Shut Down not demanded
	-			CVJ-NIU	332/26-28	220			-		SEB for maintenance wor
	0 B	RC	ST-BRC	CVJ-NIU	334/15-17	66	GETC				
	22			CVJ-NIU	334/23-25						
	23		111	CVJ-NIU	336/23-25		to be a		13/12		
	24			CVJ-NIU	336/25-27		The second second				
	25			VRE-PLJ	349/25-27 356/19-21		-				
1	26			PLJ-LKD	357/5-7	22	GETC	0		-	
	27		1	F_J-LKD LKD-MYG	359/1-3	22	and the same of th	0		-	
	28		8	LKD-MYG	365/1-364/	29 56	GETO	0			
3	29		6		367/29-3	66	GETO	0			
-	30		1	MYG-KSPF VRM-MPR	And the second second		0 GETC			-	
<u> </u>	31			VRM-MPR		- 0	GET	and the same of th			
_	32		1	VRM-MPR			2 GETO	00	-	-	
	33			MPR-VS	387/33-38	-					
L				11-00-00-00-00-00-00-00-00-00-00-00-00-0	388/7-9	6				-	
	35		1	MPR-VS BJW-BRC			32 GET			-	
L	36		1	CHORD LIN	The second secon	0 13	32 GET	-	3	-	
L	37			BRC D-BJ		-	6 GET	CO	-		
	38		BRC D-BJ			6 GET	co				

.N D 10 11 142 43 44 45 46 47 48 49 50 51 52 53 554	vid	Section BRC-GER	Between Stations  BJW-RNO  BJW-RNO  BJW-RNO  BJW-RNO  BJW-RNO  RNO-VDA  RNO-VDA  RNO-VDA	Location 405/33-406/1 406/1-3 KRCA/1592- 1594 KRCA/3596- 1600 KRCA/1594- 2596 406/1-3 409/11-13 409/13-15	Line Voltage in KV  132  132  132  132  132  132  132  13	Owned by  GETCO GETCO GETCO GETCO	Date of maint 20.11.14	13.55	To 15.00	Remarks
41 42 43 44 45 46 47 48 49 50 51 52 53 54		BRC-GER	BJW-RNO BJW-RNO BJW-RNO BJW-RNO RNO-VDA RNO-VDA RNO-VDA	406/1-3 KRCA/1592- 1594 KRCA/3596- 1600 KRCA/1594- 2596 406/1-3 409/11-13	132 132 132 132 132	GETCO GETCO GETCO	20.11.14	13.55	15.00	
42 43 44 45 46 47 48 49 50 51 52 53 54		BRC-GER	BJW-RNO BJW-RNO BJW-RNO RNO-VDA RNO-VDA RNO-VDA	KRCA/1592- 1594 KRCA/3596- 1600 KRCA/1594- 2596 406/1-3 409/11-13 409/13-15	132 132 132 132	GETCO GETCO				
43 44 45 46 47 48 49 50 51 52 53 54		BRC-GER	BJW-RNO BJW-RNO RNO-VDA RNO-VDA RNO-VDA	1594 KRCA/3596- 1600 KRCA/1594- 2596 406/1-3 409/11-13 409/13-15	132 132 132	GETCO GETCO				
44 45 46 47 48 49 50 51 52 53		BRC-GER	BJW-RNO BJW-RNO RNO-VDA RNO-VDA RNO-VDA	KRCA/3596- 1600 KRCA/1594- 2596 406/1-3 409/11-13 409/13-15	132	GETCO				
45 46 47 48 49 50 51 52 53		BRC-GER	BJW-RNO RNO-VDA RNO-VDA RNO-VDA	KRCA/1594- 2596 406/1-3 409/11-13 409/13-15	132					
46 47 48 49 50 51 52 53		BRC-GER	RNO-VDA RNO-VDA RNO-VDA	406/1-3 409/11-13 409/13-15						
46 47 48 49 50 51 52 53		BRC-GER	RNO-VDA RNO-VDA RNO-VDA	409/13-15	132	GETCO				
47 48 49 50 51 52 53		BRC-GER	RNO-VDA	the second secon	102	GETCO				
48 49 50 51 52 53		BRC-GER			132	GETCO				
50 51 52 53		BRC-GER	MON ADD	409/21-23	66	GETCO				
51 52 53 54		BRC-GER	VDA-ADD	416/17-19	400	GETCO				
52 53 54		D110-0-11	· VDA-ADD	418/17-19	400	GETCO			-	
53 54			ADD-VXD	421/7-9	400	GETCO				
54		-	ADD-VXD	421/13-15 425/17-19	220 66	GETCO				
-			VXD-ANND VXD-ANND	425/17-19	11	MGVCL				
	- 70		VXD-ANND	426/25-27	132	GETCO				
66			KBRY-UTD	441/17-19	11 -	MGVCL				
57	- 11		KBRV-UTD	442/23-25	11	MGVCL	E Y	CHE CO		
58			KBRV-UTD	443/8-10	66	GETCO				
59		l t	KBRV-UTD	444/2-4	11	MGVCL				
50			ND-GTE	452/19-21	11	MGVCL	-		-	
51		1 [	ND-GTE	453/2B-3	66	GETCO	-		-	
62			GTE-MHD	466/10-12	11	MGVCL	-	-		
53			GTE-MHD	466/14-16	132	GETCO	-	-		
64		GTE-MHD	466/6-8 472/15-17	220	GETCO	-	-			
65		1	MHD-KANJ KANJ-BJD	475/9-11	66	GETCO				Shut Down not demanded b
66		-	BJD-GER	479/24-26	66	GETCO				SEB for maintenance work
67 68		1 1	ANND-SNA	5/6-7	400	GETCO				
69	BRC		SVL-WTPS	9/15-16	220	GETCO				
70			UMH-DK	24/2-3	66	GETCO		-		
71			UMH-DK	24/4-5	66	GETCO			-	
72		ANND-	TAS-AGCI	40/13-14	400	GETCO	1			
73		GDA	TAS-AGCI	43/11-12	220	GETCO MGVCL	-	-	-	
74		-	SVL-TBA	52/19-2C 56/15-57/1	11	GETCO				
75		100	TBA-TWA TWA-VKG	65/11-12	66	GETCO			100	
76 77			TWA-VKG	66/2 3	220	GETCO				
78			VKG-GDA	77/18-20	132	GETCO				
79			GDA-KRSA	468/7-9	132	GETCO				
80			GDA-KRSA	465/23-25	220	GETCO	-	1	-	
B1			GDA-KRSA	465/21-23	66	GETCO	-	1	-	1
82		1 1	SMLA-PIO	421/5-7	132	GETCO	+	1	-	1 7
63	100		SMLA-PIO	420/3-5 418/11-13	220 66 .	GETCO	-	1		1
84		1 - 1	SMLA-PIO SMLA-PIO	415/19-21	400	GETCO				]
85		BRC-GDA	SMLA-PIO	413/1-3	403	GETCO	13			
87			SML 4-PIO	412/15-17	223	GETCO				
88		1	SMLA-PIO	412/11-13	152	GETCO		16	-	-
69		4	SMLA-PIO	412/5-7	400	GETCO		+	1	
90		4	BRC D-PIO	406/11-13		GETCO	-	-	1	-
91			BRC D-PIO	406/5-7	132	GETCO GETCO		-		1
92		-	BRC D-PIO	402/19-21	132	GETCO				1
93	-	100	THAM-SAZ	13/5-6	220	GETCO				
94 0.E			THAM-SAZ THAM-SAZ	16/15-16	220	GETCO				
95 96	1		VGR-SAZ	29/8-9	66	GETCO	+			
97	1	23. 25.55	VGR-PKJ	31/7-8	66	GETCO	08.12.14		-	
98		BH-DHF	VGR-PKJ	31/7-8	66	GETCO	08.12.14	13.20	14.45	+
99	1		VGR-PKJ	31/8-9	66	GETCO		- 8	-	Shut Down not demanded
100			VGR-PKJ	34/5-6	66	GETCO	-	- 3	-	SEB for maintenance wor
101			PKJ-DHF DHF	47/4-5 0/2-3	65 220	GETCO GETCO	-	-	+	- SED TOT MINISTERIOR WO

_				Western	n Railway		Annexure		
	_	1	Details	of 11KV, 33K\	Power line	crossings			
S.N	Div	Section	Between Stations	Location	Trans Line Voltage in KV	Owned by	Remarks		
1		VR-ST	SJN-BLD	159/25-26	11	DGVCL			
2	BL	A CONTROL OF	VPI-UVD	174/1-2	11	DGVCL	N 7314 1824		
3		UDN-JL	USD-TPS	GEB-3/17	11	DGVCL			
4			USD-TPS	GEB-3/18	11	DGVCL			
5			PPD-SAT	491/23-26	33	MGVCL			
6			LMK-MAM	517/31-34	33	MGVCL			
7	RTM	GDA-NAD	DHD-RET	538/17-18	33	MGVCL			
8			DHD-RET	538/21-24	33	MGVCL			
9			ANS-MGN	572/25-28	11	MGVCL	Needs to be replaced by		
10		ST-BRC	SYN-KIM	287/15-17	11	DGVCL	undergrund cables		
11					VXD-ANND	425/19-21	11	MGVCL	
12			KBRV-UTD	441/17-19	11	MGVCL			
13	BRC	BRC-GER	KBRV-UTD	442/23-25	- 11	MGVCL			
4	DITO		KBRV-UTD	444/2-4	11	MGVCL			
5			ND-GTE	452/19-21	11	MGVCL			
6			GTE-MHD	466/10-12	11	MGVCL			
7		ANND-GDA	SVL-TBA	52/19-20	11	MGVCI			

					SoP Repo	ort of PGVCL		
YEAR	Qrt	FH	FA	NFH	Number of complai nts and % Complai nts Redress ed within Stipulat ed Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)
2013-	Q3	22	42	29	114700 &96.7%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	177326 & 45.19%	4.93%
14	Q4	14	22	32	123060 & 98.7%	)Loose Connection from pole b)Interruption due to line breakdowns c)Name change/ Reconnection	241285 &59.12%	1.94%
	Q1	17	41	32	239937 & 99.8%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	202417 & 59.44%	3.14%
2014- 15	Q2	38	134	53	130867 & 99.3%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	174216 & 49.44%	4.85%
	Q3	20	30	30	112340& 99.35%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	161468 & 41.27%	4.60%

					SoP Repo	ort of UGVCL		
YEAR	Qrt.	FH	FA	NFH	Number of complaints and % Complaints Redressed within Stipulated Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)
2013-	Q3	11	13	10	196628 & 99.9%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Loose wires	30281 & 50.14%	2.07%
14	Q4	11	1 6 8 85945 & 99.60.		99.60.	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	31366 & 64.34%	1.10%
	Q1	21	11	15	82642 & 95.9%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	27519 & 73.51%	1.38%
2014- 15	Q2	20	51	9	132271 & 98.45%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Name change/ Reconnection	27814 & 73.44%	2.26%
	Q3	11	4	5	102996 & 99.13%	a)Loose Connection from pole b)Interruption due to line breakdowns c) Name change/ Reconnection	33206 & 78.18%	1.37%

					SoP Repor	t of MGVCL		
YEAR	Qrt.	FH	FA	NFH	Number of complaints and % Complaints Redressed within Stipulated Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)
2013-	Q3	3	19	8	102782 & 100%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	55807 &34.91%	1.29%
14	Q4	100% from pole b)Interruption due to line breakdowns c)Stopped/defective meters		53165 & 35.72%	0.88%			
	Q1	2	11	4	206080 & 100%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	45045 & 31.98%	1.16%
2014- 15	Q2 12 33 11 149850 & 100%		a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	69046 & 64%	1.38%			
	Q3	9	10	6	102817 & 99.96%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	55748 & 67.61%	0.93%

					SoP Repo	rt of DGVCL		
YEAR	Qrt.	FH	FA	NFH	Number of complaints and % Complaints Redressed within Stipulated Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)
2013-	Q3	13	13	25	146969 & 100%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption due to failure of transformer	91549 &35.40%	2.31%
14	100% from pole b)Interruption due to line breakdowns c)Interruption due to failure of transformer		b)Interruption due to line breakdowns c)Interruption due to failure of	843668& 30.76%	0.87%			
	Q1	10	7	8	101913 & 100%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Stopped/defective meters	87702 &39.30%	1.14%
2014- 15	Q2	11	35	21	123504 & 99.4%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption due to failure of transformer	91550 & 41.12%	1.61%
	Q3	7	20	14	101542 & 99.60%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption due to failure of transformer	98873 & 46.98%	1.30%

				So	P Report of T	PL-Ahmedabad		
YEAR	Qrt.	FH	FA	NFH	Number of complaints and % Complaints Redressed within Stipulated Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)
2013-	Q3	4	0	3	63947 & 99.6%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption in power supply due to shutdowns/ load shedding/others	8921 & 100%	0.09%
14	Q4	4	1	1	53690 & 99.8%	a)Interruption due to line breakdowns b)Interruption in power supply due to shutdowns/ load shedding/others c) Stopped/ defective meters.	7849 & 100%	0.12%
	Q1	11	0	6	102283 & 99.7%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption in power supply due to shutdowns/ load shedding/others	9043 & 100%	0.32%
2014- 15	Q2	19	3	4	101228 & 99.4%	a)Loose Connection from pole b)Interruption due to line breakdowns c)Interruption in power supply due to shutdowns/ load shedding/others	8567 & 100%	0.45%
	Q3	7	0	1	58526 & 99.79%	a)Interruption due to line breakdowns b)Interruption in power supply due to shutdowns/ load shedding/others c)Loose Connection from pole - Fuse Blown	8920 & 100%	0.16%

ANNEXURE- P

ANNEXURE- P SoP Report of TPL-Surat										
YEAR	Qrt.	FH	FA	NFH	Number of complaints and % Complaints Redressed within Stipulated Time	Nature of Majority of Complaints (SoP: 003)	Number of faulty meters and % Meters Repaired during the Quarter (SoP:013)	Failure of DTR (%) (SoP: 006)		
2013-	Q3	2	0	2	4400 & 99.9%	a)Interruption due to line breakdowns b)Interruption in power supply due to shutdowns/ load shedding/others c) Stopped/ defective meters.	5415 & 98.32%	0.00%		
14	Q4	1	0	0	3324 & 99.9%	a)Interruption due to line breakdowns b)Interruption in power supply due to shutdowns/ load shedding/others c) Stopped/ defective meters.	4029 &98.51%	0.00%		
	Q1	2	0	0	5558 & 99.9%	a)Interruption due to line breakdowns b) Stopped/ defective meters. c)Bills	3967 & 98.89%	0.13%		
2014- 15	Q2	11	0	7	5705 & 100%	a)Interruption due to line breakdowns b)Stopped/defective meters. c)Bills	4310 & 98.65%	0.13%		
13	Q3	6	0	0	4281 & 99.90%	a)Interruption due to line breakdowns b)Stopped/defective meters. c) Interruption in power supply due to shutdowns/ load shedding/others	3882 & 98.91%	0.04%		

## Reliability Indices:

				Report o	f PGVCL	
Year	Qtr	Month	SAIFI	SAIDI	MAIFI	Remarks
		Oct.	12.65	12:35	16.81	
	Q3	Nov.	9.63	7:54	14.69	
2012 14		Dec.	6.40	4:13	11.05	
2013-14		Jan.	1.81	1:36	10.3	
	Q4	Feb.	1.45	1:20	8.65	
		Mar.	1.4	1:07	9.47	
		Apr.	6.35	11:30	11.45	
	Q1	May	7.37	8:42	9.65	
		June	10.32	9:45	13.02	
		July	11.96	18:15	17.19	
2014-15	Q2	Aug.	11.00	14:03	14.89	
		Sept.	10.18	16:02	13.45	
		Oct.	8.77	13:03	13.61	
	Q3	Nov.	7.41	12:21	11.85	
		Dec.	5.48	9:53	7.80	

			SoF	Report o	of UGVCL
Year	Qtr	Month	SAIFI	SAIDI	MAIFI
		Oct.	3.00	4:18	6.83
	Q3	Nov.	2.03	2:36	5.72
2042 44		Dec.	2.13	3:57	5.25
2013-14		Jan.	2.62	3:47	5.60
	Q4	Feb.	1.76	2:39	4.21
		Mar.	1.65	2:31	4.92
		Apr.	2.20	3:03	5.17
	Q1	May	3.18	5:04	6.24
		June	3.34	5:13	6.21
		July	4.38	5:58	7.04
2014-15	Q2	Aug.	3.20	3:52	6.90
		Sept.	4.00	5:12	6.90
		Oct.	2.11	3:05	6.36
	Q3	Nov.	1.91	3:57	5.66
		Dec.	2.01	3:50	5.04

			SoF	Report o	f MGVCL
Year	Qtr	Month	SAIFI	SAIDI	MAIFI
		Oct.	5.55	6:39	23.76
	Q3	Nov.	2.99	4:07	19.52
2012 14		Dec.	3.46	6:12	17.63
2013-14		Jan.	4.99	4:40	24.25
	Q4	Feb.	2.68	2:28	16.07
		Mar.	2.64	1:59	19.51
		Apr.	4.06	5:04	19.38
	Q1	May	5.00	7:19	19.67
		June	6.95	8:34	22.55
		July	8.76	7:20	25.89
2014-15	Q2	Aug.	5.97	4:43	22.33
		Sept.	6.14	4:56	21.80
		Oct.	3.82	4:30	20.79
	Q3	Nov.	3.70	6:29	17.88
		Dec.	3.51	6:32	14.78

			SoF	Report o	f DGVCL	
Year	Qtr	Month	SAIFI	SAIDI	MAIFI	Remarks
		Oct.	9.66	13:48	22.14	
	Q3	Nov.	7.30	10:56	18.95	
2012 14		Dec.	6.81	10:09	15.25	
2013-14		Jan.	10.66	13:13	21.08	
	Q4	Feb.	6.73	10:05	13.29	
		Mar.	6.30	7:00	15.75	
		Apr.	7.36	9:07	16.48	
	Q1	May	7.98	12:00	18.78	
2014 15		June	13.74	17:35	31.80	
2014-15		July	14.19	16:53	32.82	
	Q2	Aug.	10.33	10:40	25.36	
		Sept.	9.85	12:44	23.18	
	Q3	Oct.	7.27	8:06	20.48	
		Nov.	5.95	8:46	16.14	
		Dec.	5.48	8:29	13.68	

			SoP	Report of	TPL-Ahd.	
Year	Qtr	Month	SAIFI	SAIDI	MAIFI	Remarks
		Oct.	0.44	0:32	0.01	
	Q3	Nov.	0.25	0:17	0.00	
2012 14		Dec.	0.39	0:28	0.00	
2013-14		Jan.	0.69	0:50	0.00	
	Q4	Feb.	0.4	0:33	0.00	
		Mar.	0.37	0:26	0.00	
		Apr.	0.46	0:34	0.02	
	Q1	May	0.76	0:50	0.01	
2014 15		June	0.93	0:55	0.02	
2014-15		July	0.56	0:39	0.02	
	Q2	Aug.	0.38	0:25	0.00	
		Sept.	0.31	0:24	0.01	
	Q3	Oct.	0.27	0:20	0.00	
		Nov.	0.37	0:27	0.00	
		Dec.	0.35	0:26	0.00	

	SoP Report of TPL-Surat										
Year	Qtr	Month	SAIFI	SAIDI	MAIFI	Remarks					
		Oct.	0.00	0:01	-						
	Q3	Nov.	0.04	0:01	-						
2012 14		Dec.	0.01	0:01	-						
2013-14		Jan.	0.02	0:01	0.00						
	Q4	Feb.	0.07	0:03	0.00						
		Mar.	0.02	0:01	0.00						
		Apr.	0.02	0:01	0.00						
	Q1	May	0.00	0:01	0.00						
2014 15		June	0.03	0:01	0.00						
2014-15		July	0.04	0:01	0.00						
	Q2	Aug.	0.04	0:01	0.00						
		Sept.	0.04	0:01	0.00						
		Oct.	0.06	0:03	-						
	Q3	Nov.	0.01	0:01	-						
		Dec.	0.08	0:04	-						



ANNEXURE- Q

Performance Reports Received from CGRFs for the Quarter- II of 2014-15 (Jul.-Sept.14)

Name e Pen at the of tl	Grievanc e Pending at the end of the previous	Grievance received during the Qtr.	Total Grievan ces	Grievanc es redressed during the Qtr.	Grievances successfully redressed during the Qtr.		Balance Grievances to be Redressed at the end of the Qtr.	Grieva nc es pendi ng for more than	No. of Grievances in Favour of Licensee	No. of Grievan ces in Favour of Consu mers	Others	Number of Sittings
	Qui.				Within After							
					45 days	45 days		45 days				
UGVCL	6	33	39	25	25	0	14	0	8	15	2	11
MGVCL	5	41	46	36	36	0	10	0	16	20	0	12
DGVCL	2	53	55	53	53	0	2	0	14	18	21	13
PGVCL (Bhuj)	3	20	23	21	20	1	2	0	13	8	0	8
PGVCL (Bhavnagar	33	79	112	89	50	39	23	1	37	52	0	13
PGVCL (Rajkot)	43	114	157	126	101	25	31	3	30	69	27	18
TPL (Ahm)	10	66	76	62	61	1	14	0	49	13	0	13
TPL (Surat)	0	13	13	13	13	0	0	0	6	0	7*	13
Total	102	419	521	425	359	66	96	4	173	195	57	101

Note: '\*': 7 cases are withdrawn by consumers

ANNEXURE- Q

Details of Cases before Ombudsman for Quarter II of 2014-15 (Jul. to Sept.14)

No. of Appeals Pending at the Beginning of the Quarter	No. of Appeals	Total	Dispo	No. of Aposed Off Durin	No. of Appeals	No. of		
	Received During this Quarter	Total No. of Appeals	In favour of Appellant	In favour of Licensee	Others	Total	Pending at the End of the Quarter	Sittings in the Quarter
21	40	61	22	20	9	51	10	60

ANNEXURE- Q

Performance Reports Received from CGRFs for the Quarter- III of 2014-15 (Oct.-Dec.14)

Forum Name	Grievanc e Pending at the end of the previous	Grievance received during the Qtr.	Total Grievan ces	Grievanc es redressed during the Qtr.	Grievances successfully redressed during the Qtr.		Balance Grievance s to be Redressed at the end of the	Grieva nc es pendin g for more	No. of Grievances in Favour of Licensee	No. of Grievan ces in Favour of Consum	Others	Numbe r of Sitting s
	Qtr.				Within 45 days	After 45 days	Qtr.	than 45 davs		ers		
UGVCL	14	44	58	39	39	0	19	0	14	6	19	11
MGVCL	10	31	41	33	32	1	8	0	15	18	-	8
DGVCL	2	36	38	33	33	0	5	0	10	16	7	10
PGVCL (Bhuj)	2	17	19	15	15	0	4	1	5	5	5	8
PGVCL (Bhavngr)	23	91	114	88	52	36	26	2	34	50	4	13
PGVCL (Rajkot)	31	134	165	89	74	15	76	3	21	44	24	14
TPL (Ahm)	14	50	64	56	54	2	8	0	49	7	0	12
TPL (Surat)	0	4	4	4	4	0	0	0	1	0	3	13
Total	96	407	503	357	303	54	146	6	149	146	62	89

ANNEXURE- Q

Details of Cases before Ombudsman for Quarter III of 2014-15 (Oct. to Dec.14)

No. of Appeals Pending at the Beginning of the Quarter	No. of Appeals	Total No. of Appeals	Dispo	No. of A	No. of Appeals	No. of		
	Received During this Quarter		In favour of Appellant	In favour of Licensee	Others	Total	Pending at the End of the Quarter	Sittings in the Quarter
10	43	53	12	25	3	40	13	56